


**Fermi National Accelerator Laboratory
Batavia, IL 60510**

**LHC DFBX INSTRUMENT DUCT (MBX2)
WELDMENT & WIRING
ASSEMBLY**



**Reference Drawing(s):
LHC DFBX Instrument Duct
Weldment & Wiring Assembly
ME-418185**

Project # / Task #: _____ **Job #:** _____

Released by: _____ **Magnet/Device Series:** _____

Date: _____ **Scan Pages:** _____

Prepared by: B. Jensen

| Title | Signature | Date |
|------------------------------|--|--------------------------------------|
| TD / E&F Process Engineering | <p align="center"><i>Bob Jensen</i> Bob Jensen / Designee</p> | <p align="center">1/9/04</p> |
| TD / D&T Assembly | <p align="center"><i>Dan Eddy</i> Dan Eddy / Designee</p> | <p align="center">1/12/04</p> |
| TD / D&T Fabrication Manager | <p align="center"><i>Fred Lewis</i> Fred Lewis / Designee</p> | <p align="center">1/9/04</p> |
| TD / D&T Project Engineer | <p align="center"><i>Clark Reid</i> Tom Peterson / Designee</p> | <p align="center">1/13/04</p> |

Revision Page

| <u>Revision</u> | <u>Step No.</u> | <u>Revision Description</u> | <u>TRR No.</u> | <u>Date</u> |
|-----------------|-----------------|-----------------------------|----------------|-------------|
| None | N/A | Initial Release | N/A | 1/9/04 |

Ensure appropriate memos and specific instructions are placed with the traveler before issuing the sub traveler binder to production.

1.0 General Notes

- 1.1 White (Lint Free) Gloves (Fermi stock 2250-1800) or Surgical Latex Gloves (Fermi stock 2250-2494) shall be worn by all personnel when handling all product parts after the parts have been prepared/cleaned.
- 1.2 All steps that require a sign-off shall include the Technician/Inspectors first initial and full last name.
- 1.3 No erasures or white out will be permitted to any documentation. All incorrectly entered data shall be corrected by placing a single line through the error, initial and date the error before adding the correct data.
- 1.4 All Discrepancy Reports issued shall be recorded in the left margin next to the applicable step.
- 1.5 Personnel shall perform all tasks in accordance with current applicable ES&H guidelines and those specified within the step.

2.0 Parts Kit List


- 2.1 No Parts Kit required.

3.0 Assembly & Welding

3.1 Acquire the following components and complete the assembly by welding components together in accordance with Dwg ME-418185.

Note: All components must be thoroughly cleaned with Isopropyl Alcohol (Fermi stock 1920-0300) or approved equivalent prior to welding.

| | | |
|-----------|--|------|
| MB-418174 | Top Plate – Closure Flange | 1 ea |
| MC-418171 | Flex Hose Assembly (MQX2)(1 of 2) | 1 ea |
| MB-418169 | ½' Tube Lateral Fitting | 1 ea |
| MB-418172 | Flex Hose Assembly (MBX2)(2 of 2) | 1 ea |
| MB=418176 | D1 Interconnect Flange | 1 ea |
| Item #6 | Tube, 1/2" O.D. x 0.049" x 2 1/2" long | 1 ea |
| Item #7 | Blank-Off | 1 ea |



DFBX Weldment (DNH)
 (Show without wires for clarity)
 (Show without Thermal Intercept Block)

 Technician(s)

 Date


3.2 Perform a Vacuum Leak Check of the DFBX Tube Assembly and record results below.

| PART NO. | | SCALE UNITS BEFORE HELIUM PROBE | SCALE UNITS WHILE ENCLOSURE FLOODING | DETERMINATION OF MINIMUM DETECTABLE LEAK | | | | |
|-----------|----------------------|---------------------------------|--------------------------------------|---|--|--|--|--|
| DATE TIME | OPERATOR'S LAST NAME | | | MDS 4 ((Response -Bckgnd) 4 Leak Value) = MDL | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

 Inspector

 Date

- 3.3 Stamp the serial number on the bottom of this traveler using approved methods onto the DFBX Instrument Duct Weldment & Wiring Assembly as shown below.



DFBX Weldment (DH)
(Show without wires for clarity)
(Show without Thermal Intercept Block)

Technician(s)

Date

4.0 Wire Harness Assembly

4.1 Process and assemble the following wire packages in accordance with Dwg ME-418185.

Note: Each individual wire must be labeled prior to assembly as per attached spreadsheet. Labeling should be half way from D1 Interconnect Flange to the end of the wire bundle. Labeling should be half way from Top Plate-Closure Flange and end of wire bundle after wire bundle is inserted into Instrument Duct. (See Step 4.4 & 6.1)

Note: ~ 1 twist/ 3 in –individual cables are **12** feet in length prior to twisting.

| Item | Color | Gauge | Description | Wire Count | Spares | Completed by Technician |
|------|--------|-------|-----------------------------|------------------------------|---------|-------------------------|
| #10 | Red | 20 | Quench Protection Twisted | 4 wires (2 twisted pairs) | 1 pair | |
| #11 | Orange | 26 | Warm-Up Heaters Twisted | 4 wires (2 twisted pairs) | 2 wires | |
| #12 | Orange | 26 | Dipole Voltage Taps Twisted | 6 wires (3 wires twisted) | | |
| #13 | Gold | 30 | Temperature Sensors | 8 wires (2 pairs) | 1 wire | |

The below list is for labeling of the wires.

| | MBX2 | Technician | Technician |
|------------|-----------------|--------------------------|------------------------|
| CERN Label | Description | Top Plate Closure Flange | D1 Interconnect Flange |
| EE111 | Voltage Tap | | |
| EE112 | Voltage Tap | | |
| EE131 | Voltage Tap | | |
| EE132 | Voltage Tap | | |
| EE151 | Voltage Tap | | |
| EE152 | Voltage Tap | | |
| YT111+ | Cryo Heaters | | |
| YT111- | Cryo Heaters | | |
| YT112+ | Cryo Heaters | | |
| YT112- | Cryo Heaters | | |
| EH831+ | Warm-up Heaters | | |
| EH831- | Warm-up Heaters | | |
| EH832+ | Warm-up Heaters | | |
| EH832- | Warm-up Heaters | | |
| TT831 | RTDS | | |
| TT832 | | | |

Technician(s)

Date

4.2 Assemble the wire packages and secure into a bundle.

Technician(s)


Date

4.3 Install wire package into DFBX Duct Assembly.

Technician(s)

Date

4.4 Labels on individual wire on both ends should be 3 inches from the end of the wires prior to potting. Also, put tape around wire bundle after labeling.




Note: See Step 4.1 for labeling spreadsheet.

Technician(s)

Date

4.5 Prepare the wire bundle for hipotting by performing the following:



- 4.5.1 Check for continuity between all wire and for shorts between RTD wires.
- 4.5.2 Place Kapton Tape on wire ends to prevent shorting.
- 4.5.3 Wrap entire lengths of excess wire extending out from both ends of the tube with aluminum foil.
- 4.5.4 Wrap wire around both ends of the tube extending over the foil to make a connection between foil and tube.
- 4.5.5 Follow Hipot Form until all Hipots are completed (See Step 4.5).
- 4.5.6 If wire(s) fail Hipot, determine which one(s) are bad, remove from the tube and install new one(s).
- 4.5.7 After Hipot is determined good, remove aluminum foil and attach wire.
- 4.5.8 Put glass tape around the labels on the non-connector end to protect them.

Technician(s)

Date

4.6 Electrically check the wire bundle by performing a hipot and record results below.

| Hipot | All Others Grounded | All Other Floating | Trip Voltage | 5.0 Kv/Current | Comments |
|---------------------------------|---------------------|--------------------|--------------|----------------|----------|
| VTAPS | X | | | | |
| VTAPS | | X | | | |
| | | | | | |
| RTD's (to 300V) | X | | | | |
| RTD's (to 300V) | | X | | | |
| | | | | | |
| CRYO HEATERS (Warm-Up Heaters) | X | | | | |
| CRYO HEATERS (Warm-Up Heaters) | | X | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | X | | | | |
| Pair #2 | X | | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | | X | | | |
| Pair #2 | | X | | | |
| | | | | | |
| Spare VTAP Wire(2) | X | | | | |
| Spare VTAP Wire (2) | | X | | | |
| | | | | | |
| Spare Heater Wires (1 pair) | X | | | | |
| Spare Heater Wires (1 pair) | | X | | | |
| | | | | | |
| Spare RTD Wire (1) | X | | | | |
| Spare RTD Wire (1) | | X | | | |

Technician(s)

Date

5.0 Material Development Lab

5.1 Prepare DFBX Instrument Duct for Pre-Cast Dam and Epoxy Plug. Process Pre-Cast Dam and Epoxy Lug in accordance with ME-418185 and other approved methods.

Note: Ensure proper Wire Bundle Length of **39"** is maintained from Wire Bundle ends and DFBX Instrument Duct Weldment Assy as per Dwg ME-418185.

Technician(s)

Date

6.0 Final Assembly

6.1 Move wire labels on both ends to ~ half way between wire ends and flanges.

6.2 Check each wire for continuity including spares.

Technician(s)

Date

6.3 Perform a hipot check.

| Hipot | All Others Grounded | All Other Floating | Trip Voltage | 5.0 Kv/Current | Comments |
|---------------------------------|---------------------|--------------------|--------------|----------------|----------|
| VTAPS | X | | | | |
| VTAPS | | X | | | |
| | | | | | |
| RTD's (to 300V) | X | | | | |
| RTD's (to 300V) | | X | | | |
| | | | | | |
| CRYO HEATERS (Warm-Up Heaters) | X | | | | |
| CRYO HEATERS (Warm-Up Heaters) | | X | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | X | | | | |
| Pair #2 | X | | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | | X | | | |
| Pair #2 | | X | | | |
| | | | | | |
| Spare VTAP Wire(2) | X | | | | |
| Spare VTAP Wire (2) | | X | | | |
| | | | | | |
| Spare Heater Wires (1 pair) | X | | | | |
| Spare Heater Wires (1 pair) | | X | | | |
| | | | | | |
| Spare RTD Wire (1) | X | | | | |
| Spare RTD Wire (1) | | X | | | |

Technician(s)

Date


6.4 Bend the DFBX Instrument Duct Assembly as per Dwg ME-418185.

Technician(s)

Date

6.5 Acquire the Blank Off (Item #7 – Dwg ME-418185) and weld onto tube.

Note: All components must be thoroughly cleaned with Isopropyl Alcohol (Fermi stock 1920-0300) or approved equivalent prior to welding.



**DFBX Instrurment Duct
(Top View)
(Shown without wire for clarity)**

Technician(s)

Date

6.6 Perform a Vacuum Leak Check of the DFBX Tube Assembly and record results below.

| PART NO. | | SCALE UNITS BEFORE HELIUM PROBE | SCALE UNITS WHILE ENCLOSURE FLOODING | DETERMINATION OF MINIMUM DETECTABLE LEAK | | | | |
|-----------|----------------------|---------------------------------|--------------------------------------|---|--|--|--|--|
| DATE TIME | OPERATOR'S LAST NAME | | | MDS 4 ((Response -Bckgnd) 4 Leak Value) = MDL | | | | |
| | | | | | | | | |
| | | | | | | | | |

Inspector

Date

6.7 Electrically check the wire bundle by performing a hipot and record results below.

Note: See Step 4.4 for proper preparations for Hipot.

| Hipot | All Others Grounded | All Other Floating | Trip Voltage | 5.0 Kv/Current | Comments |
|------------------------------------|---------------------|--------------------|--------------|----------------|----------|
| VTAPS | X | | | | |
| VTAPS | | X | | | |
| | | | | | |
| RTD's (to 300V) | X | | | | |
| RTD's (to 300V) | | X | | | |
| | | | | | |
| CRYO HEATERS (Warm-Up Heaters) | X | | | | |
| CRYO HEATERS (Warm-Up Heaters) | | X | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | X | | | | |
| Pair #2 | X | | | | |
| | | | | | |
| Strip Heaters (Potted In Pairs) | | | | | |
| Pair #1 | | X | | | |
| Pair #2 | | X | | | |
| | | | | | |
| Spare VTAP Wire(2) | X | | | | |
| | | | | | |
| Spare Heater Wires (1 pair) | X | | | | |
| | | | | | |
| Spare RTD Wire (1) | X | | | | |
| | | | | | |

Technician(s)

Date

6.8 Prepare the DFBX Instrument Duct/Wiring Assembly for shipment by performing the below:

6.8.1 Tape the wire bundle to the Instrument Duct Tube on both ends.




Figure 1

Technician(s)

Date

7.0 Production Complete

7.1 Process Engineering verify that the LHC DFBX Instrument Duct Assembly Traveler is accurate and complete. This shall include a review of all steps to ensure that all operations have been completed and signed off. Ensure that all Discrepancy Reports, Nonconformance Reports, Repair/Rework Forms, Deviation Index and dispositions have been reviewed by the Responsible Authority for conformance before being approved.

Comments:

Process Engineering/Designee

Date