Document ID: 7890

LHC Q1 LMQXA Cold Mass Module Assembly Traveler

333754 / Rev. F

Job No:	**248**
E + F Project/Task No.:	**300/1.1.1.6.3**
M + S Project/Task No.:	**300/1.1.1.6.2**

Place This Side Down For Scanning!!!

Magnet Travelers

LMQXA08-0

Document ID:

7890

Job No.:

248

Project/Task No.

300/1.1.1.6.3

Series:

LQXA

Serial No:

LMQXA08

Rework ID:

0

Specification No.:

333754

Revision:

F

LMQXA08-0

Fermi National Accelerator Laboratory
Batavia, IL 60510

LARGE HADRON COLLIDER
Q1 - LMQXA
COLD MASS MODULE ASSEMBLY TRAVELER

Reference Drawing(s):
Q1 Cold Mass Welded Assembly (ME-390526)
Q1 Module Assembly (ME-369894)

Project/Task Number: *300/1.1.1.6.2*

Released By: *John Szostak* **Magnet/Device Series:** *LQXA*

Date Issued: *5/13/2005 10:09:17 AM* **Scanned Pages:** 110

Prepared by: J. Szostak

Title	Signature	Date
TD / E&F Process Engineering	*Jamie Blowers* Bob Jensen / Designee	*2/28/05*
TD / LHC Production Supervisor	*Jim Rife* Jim Rife / Designee	*2/28/05*
TD / LHC Production Engineer	*Rodger Bossert* Rodger Bossert / Designee	*2/28/05*
TD / LHC Project Engineer Cryostat	*Tom Nicol* Tom Nicol / Designee	*2/28/05*
TD / LHC Project Physicist	*Mike Lamm* Michael Lamm / Designee	*2/28/05*
TD / LHC Program Manager	*Jim Kerby* Jim Kerby / Designee	*2/28/05*

Revision Page (1 of 4)

Revision	Step No.	Revision Description	TRR No.	Date
None	N/A	Initial Release	N/A	10/17/03
A	4.3	Modified Step. Changed to "Configure tooling for End Dome Mounting per (ME-369765, View E-E.)"	1580	2/19/04
	4.5	Modified Step. Changed to "Rotate the Q1 Cold Mass, with the Power Leads facing down, into the proper orientation as shown in Figure 4.5-A." Added New Figure from Rodger Bossert.		
	4.6	Modified Step. Changed to "Perform a stretched wire measurement of the system to align the Cold Mass within ± .2 mR." Changed Signoff to Responsible Authority/Physicist.		
	4.7	Added Step. "Mount the Corrector Coil Mounting Ring (ME-390037) to the Corrector Coil (MD-390312)."		
	4.7	Modified Step. Changed to "Weld Correction Coil Mounting Flange (ME-390037) to Q1 Lead End Plate." (New Step 4.10)		
	4.8	Added Step. "Position and align the Corrector Coil (MD-390312)."		
	4.9	Added Step. "Tack weld the Corrector Coil Mounting Ring (ME-390037) to the Q1 Cold Mass Assembly per Q1 Coldmass Welded Assembly (ME-390526)."		
	4.11	Added Step. "Disassemble the Corrector Coil (MD-390312) from the Corrector Coil Mounting Ring (ME-390037)."		
	5.0	Modified Step. Replaced Figure 5.0-A with New Figure from Rodger Bossert.		
	5.11	Modified Step. Changed to "Construct / Obtain Expansion Loop Assembly per Drawing (MB-369962)." **(New Step 5.2)**		
	5.11	Added Step. "Weld Warm-up Heater Base Plates (MA-360007) and RTD Mount Blocks to End Plates as per Q1 Module Assembly (ME-369894)." **(New Step 5.11)**		
	5.12	Modified Step. Changed to "Solder the lower 8kA bus to Lower Lead as per Q1 Module Assembly Drawing (ME-369894) and Figure **5.0-B**." **(New Step 5.3)**		
	5.13	Modified Step. Changed to "Solder the upper 8kA bus to Upper Lead as per Q1 Module Assembly Drawing (ME-369894) and Figure **5.0-B**." **(New Step 5.4)**		
	5.17	Modified Step. Changed to "Attach Q1 Bus Exit Support Part Numbers to Q1 Lead as per Q1 Module Assembly (ME-369894)." **(New Step 5.8)**		
	5.18	Modified Step. Added Note: "**USE ONLY CERN LABELS ON WIRES.**" Added New Table from Rodger Bossert. **(New Step 5.9)**		
	5.19	Modified Step. Changed to "...Verify that there is sufficient slack in cable to allow for two inches of differential thermal contraction." Replaced Figures with New Figures from Rodger Bossert. **(New Step 5.10)**		
	5.20.1	Removed Step. "Install Warm-up Heater Base Plates (MA-369997) by welding onto in End Plate. (Check each box as Heater is installed.)"		
	5.21.1	Modified Step. Changed to "Attach RTD's (MA-369835) (Qty. 2) to Mounting Blocks as per Q1 Module Assembly (ME-369894)." **(New Step 5.13.1)**		
	5.22	Modified Step. Added "Record the resistance data from the Manufacturer's Traveler below. Compare RTD resistance test results to the resistance results from the Manufacturer's Traveler. Ensure RTD resistances are within **5Ω**. Attach the Manufacturer's RTD papers at the end of this traveler." Modified Tables to show comparison of RTD resistance. Deleted Wire Nos. from Table. Only CERN Labels will be used. **(New Step 5.14)**		

Revision Page (2 of 4)

Revision	Step No.	Revision Description	TRR No.	Date
A (continued)	5.23	Modified Step. Changed to "Hipot RTD's to 100V. Use Droege Serial No. 910 (FNAL Part No. 51330) or equivalent. Hipot Cryogenic (Warmup) Heaters to 300V. Use Droege Serial No. 910 (FNAL Part No. 51330) or equivalent." Modified Tables to show comparison of Hipot Leakage. Deleted Wire Nos. from Table. Only CERN Labels will be used. **(New Step 5.15)**	1580 (continued)	2/19/04
	5.23	Added Step. "Tack weld bolts and washers for mounting Corrector into place per Q1 Cold Mass Welded Assembly (ME-390526)."		
	5.24	Modified Step. Changed to "Attach Linear Cable Clamp Assembly (ME-430040) to bottom of corrector Magnet." **(New Step 5.16)**		
	5.26	Modified Step. Changed to "Attach the MCBX Corrector Magnet Alignment Tooling (ME-390390) to the MCBX Corrector Magnet (MD-390312). ..." **(New Step 5.18)**		
	5.27	Added Step. "Verify that Top Surface of the Bus as it exits the Magnet is also at the top as it exits the Linear Cable Clamp Assembly."		
	5.28	Added Step. "Attach the Backing Spline (MD-430053) to the Expansion Loop, between the Stabilizer Assembly and the Linear Cable Clamp Assembly, as shown on Q1 Module Assembly (ME-369894)."		
	5.29	Added Step. "Wrap Glass Tape and Kevlar String on the area between the magnet and the Linear Cable Clamp Assembly."		
	5.29	Modified Step. Changed to "Move the MCBX Corrector Magnet (MD-390312) up against the Mounting Ring on the Q1 Magnet, and bolt the MCBX Correction Coil (MD-390312) to the Q1 Cold Mass using the Silver Plated Mounting Screw (MA-390247) and torque bolts to 500 in-lbs. per Note 4 of Q1 Cold Mass Welded Assembly (ME-390526). Shim between the Corrector and Flange as necessary." **(New Step 5.21)**		
	5.30	Added Step. "Attach Face Plate for Corrector Leads (MD-390671) to front surface of Correction Coil."		
	5.32	Modified Step. Added "...The Top of the Bus as it exits the Magnet should face toward the Cold Mass at the stabilizer assembly." **(New Step 5.25)**		
	5.33	Modified Step. Added "...Bus surface facing Cold Mass at stabilizer assembly should be at top as it exits the linear cable clamp assembly." **(New Step 5.26)**		
	5.35	Added Step. "Attach Backing Spline (MD-430053) to area between Linear Cable Clamp Assembly and Lead End Spider Assembly (MD-430042)."		
	5.36	Added Step. "Wrap Glass Tape and Kevlar String on the area between the Linear Cable Clamp Assembly and the Lead End Spider Assembly (MD-430042)."		
	5.37	Modified Step. Changed to "Attach Q1 Lead End Spider Assembly (MD-430042) to Lead Bus (MB-369962) and Corrector Coil Bus as shown in Q1 Module Assembly (ME-369894)." New Step 5.34.		
	6.1	Modified Step. Changed to New Electrical Step by Rodger Bossert.		
	8.1	Modified Step. Changed Part numbers: Beam Tube (MD-369955) and Insulated Beam Tube Assembly for Q1 (MD-369746)."		
	8.3	Modified Step. Changed Part number: Beam Tube (MD-369955).		
	8.4	Modified Step. Changed Part number: Beam Tube (MD-369955).		
	8.5.2	Modified Step. Changed to "Subtract 7725 mm (± 2mm) from the Beam Tube Length, and record here:"		
	9.2	Removed Step. "If needed, perform a stretched wire measurement of the system, noting the relative position and roll of the three magnetic elements to each other." per Tom Page.		

Revision Page (3 of 4)

Revision	Step No.	Revision Description	TRR No.	Date
A (continued)	11.0	Modified Step. Changed to New Electrical Step by Rodger Bossert.	1580 (continued)	2/19/04
	12.0	Modified Step. Changed Hypertronics Labels.		
	12.2	Added Step. "Contact LHC Project Physicist / designee and obtain signature before Hypertronics Cover is installed."		
	12.3	Added Step. "After LHC Project Physicist / designee has signed the above step, complete the installation of the Hypertronics."		
	13.0	Modified Step. Changed to New Electrical Step by Rodger Bossert.		
	3.2	Added Step. "Attach the Certificate of Conformity, for vendor supplied components, and the Quality Record, for vendor supplied components, to this traveler. Verify that the Certificate of Conformity and /or the Quality Record (as required) has been filled out and performed by Fermilab personnel."		
B	1.5	Removed Step. "All personnel performing steps in this traveler must have documented training for this traveler and associated operating procedures."	1612	6/4/04
	5.17	Removed Step. "Place the MCBX Correction Coil (MD-390312) in the Corrector Magnet Mounting Tooling."		
	5.18	Removed Step. "Attach the MCBX Corrector Magnet Alignment Tooling (ME-390390) to the MCBX Corrector Magnet (MD-390312). Align the Scribe Lines on the Corrector Magnet (MD-390312) with those on the tooling."		
	5.19	Removed Step. "Mount the Mini Level to the top of the MCBX Corrector Magnet Alignment Tooling"		
	5.20	Removed Step. "Rotate the MCBX Correction Coil (MD-390312) such that the Mini Level is Horizontal 0.00 mm/m (+/- 0.05 mm/m)."		
	5.22	Modified Step. Added Technician Signoff for alignment. (New Step 5.18)		
	5.28	Added Step. "Add Mount to Face Plate"		
	5.29	Added Step. "Place Voltage taps as follows: "		
	7.12	Added Step. "Mount the KEK Cold Mass Leveling Bracket (MD-390711) to the X side of the magnet. Record the serial number of the mini level that will be used below." Per Tom Page.		
	7.13	Added Step. "Adjust the mini level so that it is level with respect to gravity. See the mini level instructions for this procedure."		
	7.14	Added Step. "Place the mini level on the leveling bracket so that the readout is facing the Non-IP end (corrector end) of the magnet. Push the level up against the leveling bracket top screws. Record the Magnet Level here" Per Tom Page.		
	7.15	Added Step. "Remove the mini level but leave the KEK Cold Mass Leveling Bracket (MD-390711) mounted to the Cold Mass." Per Tom Page.		
	7.16	Added Step. "Move Coldmass to the Assembly Table"		
	8.2	Removed Step. "Verify Alignment of Q1 and Corrector Magnet (MD-390312) as per Q1 Cold Mass Welded Assembly (ME-390526)." Task completed in step 5.22 per Tom Page and LMQXA01.		
	8.4	Added Step. "Place a mark 40mm from the laminations on IP End of the Beam Tube."		
	8.5 – 8.11	Removed Steps. Steps removed per Tom Page.		
	8.5	Added Step. "Verify that the placement of the mark in Step 8.4 is correct."		
	8.6	Added Step. "Using the Wachs Cutter, cut the IP End of the Beam Tube at the mark."		
	8.7	Added Step. "Measure the Beam Tube length and record this measurement below."		
	8.8	Added Step. "Using the number recorded in Step 8.7.2, measure and place a mark at the Non-IP End of the Beam Tube."		

Revision Page (4 of 4)

Revision	Step No.	Revision Description	TRR No.	Date
B (Continued)	8.9	Added Step. "Verify that the placement of the mark in Step 8.8 is correct."	1612 (Continued)	6/4/04
	8.10	Added Step. "Using the Wachs Cutter, cut the Non-IP End of the Beam Tube at the mark."		
	8.11	Added Step. "Measure and verify Beam Tube length is 7725 (+0/-4mm). Record Actual Beam Tube Length below."		
	10.0	Added Step. Suspension System Assembly Step moved from Q1 Cryostat Final Assembly Traveler. New Steps added per Tom Page.		
C	5.14	Modified Step. Modified Tables.	1648	7/14/04
	5.15	Modified Step. Added "(Max. Leakage < 0.1 μA)" Modified Tables.		
	6.1	Modified Step. Added new method of measuring Ls &Q per Rodger Bossert.		
	10.18	Modified Step. Changed "East" to "IP" and "West" to "Non-IP". Deleted "Center –North" and "Center South" per LQXA01.		
	12.1	Modified Step. Added new method of measuring Ls &Q per Rodger Bossert.		
	14.1	Modified Step. Added new method of measuring Ls &Q per Rodger Bossert.		
D	6.0	Modified Step. Added new Electrical ranges / nominals per Rodger Bossert.	1657	8/10/04
	6.1	Modified Step. Changed to "2. Set test current to **0.1** amp." per LMQXA04.		
	9.1	Modified Step. Changed "corrector mounting" to "Expansion Loop Mounting " LMQXA02.		
	12.0	Modified Step. Added new Electrical ranges / nominals per Rodger Bossert.		
	12.1	Modified Step. Changed to "2. Set test current to **0.1** amp." per LMQXA04.		
	14.0	Modified Step. Added new Electrical ranges / nominals per Rodger Bossert.		
	14.1	Modified Step. Changed to "2. Set test current to **0.1** amp." per LMQXA04.		
E	5.14	Modified Cryogenic Warm-up Heater Table.	1691	12/15/04
	6.2	Modified Step. Added Picture of Corrector Bus Leads. Modified Table.		
	10.9	Modified Step. Changed to "Measure the distance between the Suspension Rings at the bottom of the Threaded Rods and record measurements below. Copy this page and place copy in designated book for later reference. (TR-333755, Q1 Cryostat Final Assembly, Step 5.1)."		
	12.2	Modified Step. Added Picture of Corrector Bus Leads. Modified Table.		
	14.2	Modified Step. Added Picture of Corrector Bus Leads. Modified Table.		
F	1.6	Added Step. "Protect the bellows during all stages of production." **DR No. HGQ-0500.**	1707	2/28/05
	4.7	Added Step. "Place the MCBX Correction Coil (MD-390312) on the Corrector Installation Carriage. Ensure orientation corresponds with Figure 4.7-A below. (Modified version of 369894, p.2)" per production request.		
	5.14	Modified Step. Changed RTD table. Swapped locations to correct location corresponding to Figure 5.10-A.		
	5.15	Modified Step. Changed RTD table. Swapped locations to correct location corresponding to Figure 5.10-A.		
	14.0	Modified Step. Removed electrical checks that are previously performed by MTF, per production request.		

Ensure appropriate memos and specific instructions are placed with the traveler before issuing the sub traveler binder to production.

1.0 General Notes

1.1 All steps that require a sign-off shall include the Technician/Technician(s)s first initial and full last name.

1.2 No erasures or white out will be permitted to any documentation. All incorrectly entered data shall be corrected by placing a single line through the error, initial and date the error before adding the correct data.

1.3 All Discrepancy Reports issued shall be recorded in the left margin next to the applicable step.

1.4 Personnel shall perform all tasks in accordance with current applicable ES&H guidelines and those specified within the step.

1.5 Cover the product/assembly with Green Herculite (Fermi stock 1740-0100) when not being serviced or assembled.

1.6 Protect the Bellows during all stages of production.

2.0 Parts Kit List

2.1 Attach the completed Parts Kit for this production operation to this traveler. Ensure that the serial number on the Parts Kit matches the serial number of this traveler. Verify that the Parts Kit received is complete.

J. Ghostah
Process Engineering/Designee

5/13/05
Date

3.0 Q1 Module Alignment

3.1 Record the serial number for each Magnetic Component Assembly.

Q1 Serial Number: MQXA-09

MCBX Serial Number: MCBX 011

Responsible Authority/Physicist

Date 5/14/05

3.2 Attach the Certificate of Conformity, for vendor supplied components, and the Quality Record, for vendor supplied components, to this traveler.
Verify that the Certificate of Conformity and /or the Quality Record (as required) has been filled out and performed by Fermilab personnel.

Crew Chief

Date 5-14-05

4.0 Q1 Magnet Placement (Module Assembly Tooling)

4.1 Configure tooling for Q1 Cold Mass Assembly (ME-390108) per Final Coldmass Assembly Stat – Support and Clamping Fixture (ME-369768).

Technician(s) _____ Date 5-14-05

4.2 Configure tooling for Corrector Mounting per Cold Mass / Cryostat Station Corrector Support Fixture (ME-369780), 13.780 Diameter Corrector Magnet.

Technician(s) _____ Date 5-14-05

4.3 Configure tooling for End Dome Mounting per Cold Mass Cryostat Station Final Assembly (ME-369765, View E-E).

Technician(s) _____ Date 5-14-05

!! LQ DR 0575 (4205)

4.4 Move the Q1 Cold Mass to the Cold Mass Module Assembly Tooling, placing it nearest the West End of ICB, with the Lead End of the Magnet facing East as per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 5-14-05

4.5 Rotate the Q1 Cold Mass, with the Power Leads facing down, into the proper orientation as shown in Figure 4.5-A.



Looking at Lead End of Q1

Figure 4.5-A

Technician(s) _____ Date 5-15-05

4.6 Perform a stretched wire measurement of the system to align the Cold Mass within ± .2 mR.

Responsible Authority/Physicist _____ Date 5-15-05

4.7 Place the MCBX Correction Coil (MD-390312) on the Corrector Installation Carriage. Ensure orientation corresponds with Figure 4.7-A below. (Modified version of 369894, p.2)



Q1 LEAD END – END VIEW

Figure 4.7-A

Technician(s) _____ Date 6/1/05

STOP

Crew Chief _____ Date 6-1-05

4.8 Mount the MCBX Corrector Mounting Ring (ME-390037) to the MCBX Correction Coil (MD-390312).

Technician(s) _____ Date 6/2/05

4.9 Position and align the MCBX Correction Coil (MD-390312).

Technician(s) _____ Date 6/2/05

4.10 Tack weld the MCBX Corrector Mounting Ring (ME-390037) to the Q1 Cold Mass Assembly (ME-390108) per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor _____ Date 6-8-05

4.11 Weld the MCBX Corrector Mounting Ring (ME-390037) to the Q1 Cold Mass Assembly (ME-390108) per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor _____ Date 6-8-05

4.12 Disassemble the Corrector Coil (MD-390312) from the MCBX Corrector Mounting Ring (ME-390037).

Technician(s) _____ Date 6/3/05

5.0 Bus & Instrumentation Connection and Assembly

Note(s):

Figure "5.0-A" shows the configuration of Magnet Bus Leads and Corrector Bus Leads in a Q1 Magnet.



View A-A (Q1 Lead Configuration)

Figure 5.0-A

5.1 Set up the Power Leads for splicing as shown in the Q1 Module Assembly Drawing (ME-369894).

Technician(s) _____ Date 6-9-05

5.2 Construct / Obtain Expansion Loop Assembly per Drawing (MB-369962).

Technician(s) _____ Date 6-9-05

5.3 Solder the Lower 8kA bus to Lower Lead as per Q1 Module Assembly Drawing (ME-369894) and Figure **5.0-B**.

Technician(s) _____ Date 6-9-05

5.4 Solder the Upper 8kA bus to Upper Lead as per Q1 Module Assembly Drawing (ME-369894) and Figure **5.0-B**.

Technician(s) _____ Date 6-9-05



Looking at Lead End of Q1

Figure 5.0-B

5.5 Insulate each splice with 2/3 overlap, .002 x 3/8 wide kapton, (MA-292722).

Ines Ramos — Technician(s) 6/6/05 — Date

5.6 Insert piece of .005 kapton between splices.

Ines Ramos — Technician(s) 6/6/05 — Date

5.7 Put splices together and insulate splice area with ¾ overlap, .002 x 3/8 wide kapton, part no. (292722).

Ines Ramos — Technician(s) 6/6/05 — Date

5.8 Attach Q1 Bus Exit Support Part Numbers to Q1 Lead as per Q1 Module Assembly (ME-369894).

[illegible] — Technician(s) 6/6/05 — Date

5.9 Prepare Q1 Instrumentation wire feed thru. Build per Q1 Module Assembly Instrumentation Wire Feedthru (ME-430008). Wire Labels and descriptions are shown in Table 5.18 and per (MB-369998).

Note(s):

USE ONLY CERN LABELS ON WIRES.

Q1 Instrumentation wire feed thru labels				
	Fermilab Label	CERN Label		Description
1	W1aQ1	EH8311+	Twist Together	Q1 Cryogenic Heater Lead "1", lead end heater (a)
2	W2aQ1	EH8311-		Q1 Cryogenic Heater Lead "2", lead end heater (a)
3	TaQ1_I+	TT8311 I+	Pre-made cable	Q1 RTD, primary Wire color: Yellow
	TaQ1_I-	TT8311 I-		Q1 RTD, primary Wire color: Green
	TaQ1_V+	TT8311 U+		Q1 RTD, primary Wire color: Black
	TaQ1_V-	TT8311 U-		Q1 RTD, primary Wire color: Red
4	TbQ1_I+	TT8321 I+	Pre-made cable	Q1 RTD, redundant: Wire color: Yellow
	TbQ1_I-	TT8321 I-		Q1 RTD, redundant: Wire color: Green
	TbQ1_V+	TT8321 U+		Q1 RTD, redundant: Wire color: Black
	TbQ1_V-	TT8321 U-		Q1 RTD, redundant: Wire color: Red



Individual Thermometer Layout



End View of Instrumentation Tube

Table 5.9

5.10 Slide Instrumentation Bus Assembly (ME-430008) into the proper Q1 Port as per Q1 Module Assembly (ME-369894). Verify that there is sufficient slack in cable to allow for two inches of differential thermal contraction.

Technician(s) _____ Date 6/3/07



Looking at Non-lead End of Q1

Figure 5.10-A



Looking at Lead End of Q1

Figure 5.10-B

5.11 Weld Warm-up Heater Base Plates (MA-360007) and RTD Mount Blocks to End Plates as per Q1 Module Assembly (ME-369894).

Weldor(s) _____ Date 5/14/05

5.12 Install Warm-up Heaters (ME-369834) to each end of Q1 as per Q1 Module Assembly (ME-369894).

5.12.1 Install Warm-up Heaters (MA-369834) onto the Warm-up Heater Base Plate (MA-369997).

5.12.2 Solder wires (MA-369833) to the Warm-up Heaters as per (ME-369894).

Technician(s) _____ Date 5/20/05

5.13 Install RTD's as per Q1 Module Assembly (ME-369894). Record Serial Numbers of each RTD in the table below. Attach Data Sheet for each RTD to traveler.

5.13.1 Attach RTD's (MA-369835) (Qty. 2) to Mounting Blocks as per Q1 Module Assembly (ME-369894).

5.13.2 Solder wires (MA-369836) to RTD's as per Q1 Module Assembly (ME-369894). Individual RTD wiring is shown in Figure 5.21.2-A below.



Figure 5.13.2-A

Technician(s) _____ Date 5/20/15

5.14 Perform a continuity check on all RTD's and Warm-Up Heaters. Record the Data below. (1mA). Record the resistance data from the Manufacturer's Traveler below. Compare RTD resistance test results to the resistance results from the Manufacturer's Traveler. Ensure RTD resistances are within **5Ω**. Attach the Manufacturer's RTD papers at the end of this traveler.

To measure the resistance of a Thermometer (RTD):

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
8. Read resistance in ohms and record in traveler.



RTD'S				
Building Temperature: 78°			**Time of Test:** 13:00	
Serial No.	**Location**	**Wire No.**	**Measured Ω**	**Mfr. Ω (expedition)**
CxCSx 17210	Q1 Inst. Non-Bus Side	TT8311	~~72.22~~ 73.76	72.22
CxCSx 17251	Q1 Inst. Bus Side	TT8321	~~66.46~~ 67.98	66.46

Cryogenic (Warm-up) Heaters			
Building Temperature: 78°		**Time of Test:** 1320	
Location	**Wire No**	**Measured Ω**	**Manufacturer Ω**
Q1 Lead End	EH8311	16.19	**16 Ω**
Q1 Non-Lead End	EH8321	16.55	**16 Ω**

Technician(s) 6/5/05 Date

5.15 Hipot RTD's to 100V. Use Droege Serial No. 910 (FNAL Part No. 51330) or equivalent. (Max. Leakage < 0.1 μA)

STOP

Have Crew Chief verify setup and sign below before continuing.

Crew Chief _____ Date 6-6-05

RTD'S			
Building Temperature: 78°			**Time of Test:** 1300
Serial No.	**Location**	**Wire No.**	**Max. Leakage < 0.1 μA**
CXLSX 17210	Q1 Inst. Non-Bus Side	TT8311	< 0.1 uA
CXLSX 17251	Q1 Inst. Bus Side	TT8321	< 0.1 uA

Hipot Cryogenic (Warm-up) Heaters to 300V. Use Droege Serial No. 910 (FNAL Part No. 51330) or equivalent. (Max. Leakage < 0.1 μA)

STOP

Have Crew Chief verify setup and sign below before continuing.

Crew Chief _____ Date 6-6-05

Warm-up Heaters		
Building Temperature: 78°		**Time of Test:** 1305
Location	**Wire No**	**Max. Leakage < 0.1 μA**
Q1 Lead End	EH8311	< 0.1 μA
Q1 Non-Lead End	EH8321	< 0.1 μA

Technician(s) _____ Date 6/5/05

5.16 Mount the Linear Clamp Base Block (MD-369926).

Technician(s) _____ Date 6-8-05

5.17 Move the MCBX Correction Coil (MD-390312) up against the Mounting Ring on the Q1 Magnet, and bolt the MCBX Correction Coil (MD-390312) to the Q1 Cold Mass using the Silver Plated Mounting Screw (MA-390247) and torque bolts to 500 in-lbs. per Note 4 of Q1 Cold Mass Welded Assembly (ME-390526). Shim between the Corrector and Flange as necessary.

Technician(s) _____ Date 6-7-05

5.18 Verify Alignment of MCBX Correction Coil (MD-390312) as per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 6-7-05

Responsible Authority/Physicist _____ Date 6/7/05

5.19 Tack weld bolts and washers for mounting Corrector into place per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) _____ Date 6/7/05

5.20 Mount the Stabilizer Assembly (ME-430039) onto the top of correction coil as shown in Q1 Module Assembly (ME-369894).

Technician(s) _____ Date 6/7/05

5.21 Feed the Lead End Loop Assembly (ME-369962) through the Stabilizer Assembly as shown in Q1 Module Assembly (ME-369894). The Top of the Bus as it exits the Magnet should face toward the Cold Mass at the stabilizer assembly.

Technician(s) _____ Date 6/7/05

5.22 Feed the Lead End Loop Assembly (ME-369962) through the Linear Cable Clamp Assembly (ME-430040)(bottom). Bus surface facing Cold Mass at stabilizer assembly should be at top as it exits the linear cable clamp assembly.

Technician(s) _____ Date 6/7/05

STOP

5.23 Verify that Top Surface of the Bus as it exits the Magnet is also at the top as it exits the Linear Cable Clamp Assembly.

Crew Chief _____ Date 6-8-05

5.24 Attach the Backing Spline (MD-430053) to the Expansion Loop, between the Stabilizer Assembly and the Linear Cable Clamp Assembly, as shown on Q1 Module Assembly (ME-369894).

Technician(s) _____ Date 6-8-05

5.25 Wrap Glass Tape and Kevlar String on the area between the magnet and the Linear Cable Clamp Assembly.

Technician(s) _____ Date 6-8-05

5.26 Attach Face Plate for Corrector Leads (MD-390671) to front surface of Correction Coil.

Technician(s) _____ Date 6-8-05

5.27 Connect the MCBX Correction Coil (MD-390312) Bus wires from Bus Assembly (ME-369826) to the MCBX Correction Coil (MD-390312) as per Q1 Module Assembly (ME-369894).

Technician(s) _____ Date 6-8-05

4257

5.28 Solder MCBX Corrector Magnet Voltage Tap Wires (MA-369832) as per Q1 Module Assembly (ME-369894).

O. Fuiay — Technician(s) — 6 13 05 — Date

5.29 Run instrumentation wire bundle along path at top of corrector coil as shown in Q1 Module Assembly (ME-369894). Attach Instrumentation Wire Hold-Down Brackets (ME-430015) as shown in Q1 Module Assembly (ME-369894) and pack with Green Putty.

Technician(s) — 6/13/05 — Date

5.30 Attach Q1 Lead End Spider Assembly (MD-430042) to Expansion Loop Assembly (MB-369962) and Corrector Coil Bus as shown in Q1 Module Assembly (ME-369894).

O. Fuiay — Technician(s) — 6 13 05 — Date

5.31 Attach Backing Spline (MD-430053) to area between Linear Cable Clamp Assembly and Lead End Spider Assembly (MD-430042).

O. Fuiay — Technician(s) — 6 13 05 — Date

5.32 Wrap Glass Tape and Kevlar String on the area between the Linear Cable Clamp Assembly and the Lead End Spider Assembly (MD-430042).

O. Fuiay — Technician(s) — 6 13 05 — Date

6.0 Electrical Inspection

6.1 Perform an electrical inspection on each of the Individual Quadrants and the Cold Mass. Refer to the Valhalla and Leader Free Standing Coil Measurement Procedure (ES-292306).

To measure the Resistance of a Q1 Cold Mass:

1. Use Valhalla Scientific 4300B digital micro-ohmmeter.
2. Set Test Current to 0.1 amp.
3. Set Scale to 2V full scale.
4. Turn temperature compensation on.
5. Turn test current off.
6. Connect I_{HI} to Q4 inner power lead as shown in figure.
7. Connect I_{LO} to Q3 inner power lead as shown in figure.
8. Turn test current on.
9. Connect V_{HI} and V_{LO} to voltage taps as shown in resistance table.
10. To measure Total with leads, connect V_{HI} to Q4 power lead and V_{LO} to Q3 power lead.
11. Read resistance and record in traveler.

Q1 Cold Mass Electrical Measurements



(Q1) Resistance				Nominal 3.35 to 3.45 Ω
Voltage Tap Serial Numbers				Total Resistance
Connect	Fermi	CERN	KEK	
V_{HI}	VTa1Q1	EE1111	a1	3.42 Ω
V_{LO}	VTc1Q1	EE1211	c1	
V_{HI}	VTc1Q1	EE1211	c1	3.42 Ω
V_{LO}	VTb1Q1	EE1311	b1	
V_{HI}	VTa1Q1	EE1111	a1	6.85 Ω
V_{LO}	VTb1Q1	EE1311	b1	
				Total Resistance with Leads
				Nominal 6.75 to 6.85 Ω
V_{HI}	Q4 Power Lead			6.85 Ω
V_{LO}	Q3 Power Lead			

C. Fiano
Technician(s)

6·14·05
Date

Check resistance of Redundant Voltage Taps.

Q1 Redundant Voltage Taps				Nominal 3.35 to 3.45 Ω
Connect	Fermi	CERN	KEK	Resistance
V_{HI}	VTa2Q1	EE1121	a2	3.42 Ω
V_{LO}	VTc2Q1	EE1221	c2	
V_{HI}	VTc2Q1	EE1221	c2	3.42 Ω
V_{LO}	VTb2Q1	EE1321	b2	

C. Fiano
Technician(s)

6·14·05
Date

To measure Ls and Q of a Q1 Cold Mass:

1. Use Agilent 4263B LCR Meter.
2. Turn power on by pushing line button. Wait 30 seconds until display screen is lit.
3. Recall program #1. To do this, push recall (Rcl), then push #1, then push Enter.
4. Push Auto/Hold button to release hold.
5. Verify that the frequency displayed in the upper right corner of the display screen is 1000 Hz and the level recorded in the lower right corner of the display screen is 1V or 1000 mV.
6. Connect H_{cur} to Quadrant 4 power lead as shown in figure.
7. Connect L_{cur} to Quadrant 3 power lead as shown in figure.
8. Connect H_{pot} and L_{pot} buttons to voltage taps as shown below.

To measure Q1:

- To measure Quadrants 1&4, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTc1 (EE1211 for Q1).
- To measure Quadrants 2&3, connect H_{pot} to VTc1 (EE1211 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).
- To measure total, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).

9. Read Ls and Q from display and record in traveler.



(Q1) Inductance				Nominal 15 to 16 mH
Voltage Tap Serial Numbers				Total Inductance
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	15.763 mH
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	15.749 mH
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 30 to 32 mH
				Total Inductance
H_{POT}	VTa1Q1	EE1111	a1	31.5 mH
L_{POT}	VTb1Q1	EE1311	b1	

(Q1) Q-Factor				Nominal 1.0 to 1.2
Voltage Tap Serial Numbers				Total Q
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	1.2
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	1.2
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 1.0 to 1.2
				Total Q
H_{POT}	VTa1Q1	EE1111	a1	1.2
L_{POT}	VTb1Q1	EE1311	b1	

O. Fuiay
Technician(s)

6·14·05
Date

To measure the resistance of a Thermometer (RTD):

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
   U+ (Black) to Sense HI
   I+ (Yellow) to Input HI
   U- (Red) to Sense LO
   I- (Green) to Input LO
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
8. Read resistance in ohms and record in traveler.



To measure the resistance of a Cryogenic (Warm-up) Heater

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
   Note: Although this is technically a 4 wire measurement, it is effectively a 2 wire measurement, since there are only 2 wires connected to each heater.
8. Read resistance in ohms and record in traveler.



Q1 - RTD's and Cryogenic (warm-up) Heaters				
Temperature of Building (± 5°): 75°				
Component	Fermi	CERN	Range	Resistance
Q1 RTD, primary	TaQ1	TT8311	60 to 70 Ω	73.9 Ω
Q1 RTD, redundant	TbQ1	TT8321	60 to 70 Ω	68.1 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at top (CERN #1 I+)	W1aQ1	EH8311+	16 to 18.5 Ω	16.18 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at bottom (CERN #1 I-)	W2aQ1	EH8311-		
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at top (CERN #2 I+)	W1bQ1	EH8321+	16 to 18.5 Ω	16.46 Ω
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at bottom (CERN #2 I-)	W2bQ1	EH8321-		

C. Friary
Technician(s)

6.14.05
Date

Using the Hewlett Packard HP3457A digital multimeter, measure the Protection (Strip) Heater Resistance for Q1.

Q1 Protection (Strip) Heater Resistance					
Fermi	CERN	KEK	Description	Range	Resistance
H1aQ1	YT1111+	HA1	Circuit A	28 to 32 Ω	28.7 Ω
H2aQ1	YT1111-	HA2			
H1bQ1	YT1121+	HB1	Circuit B	28 to 32 Ω	28.7 Ω
H2bQ1	YT1121-	HB2			

C. Friary
Technician(s)

6.14.05
Date

6.2 Using the HP4284A, connect power thru the corrector Power Leads (H1A and H1B to measure Q1-H1 or V1A and V1B to measure Q1-V1). Connect the Sense Leads as shown in table below and record resistance.

Corrector Bus Leads

	V1A	V1B	H1A	H1B

(View Looking into Q1)

Readout Labels		Power Labels	Resistance
V1A	EE8111	V1A, V1B	OF ~~85~~ .85 Ω
EE8111	V1B		~~11.5~~ OF 17.5 Ω
V1A	V1B		17.5 Ω
H1A	EE8121	H1A, H1B	17 OF .82 Ω
EE8121	H1B		21.82 Ω
H1A	H1B		21.38 Ω

C. Fi[illegible]
Technician(s)

6 15 05
Date

7.0 Dome Setup

7.1 Attach IP End Dome (MD-390172) (Q1) to the End Dome Positioning Fixture (MD-369776).

Technician(s) _____ Date 6/7/05

7.2 Align IP End Dome (MD-390172) as shown in Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 6 7 05

7.3 Level the IP End Dome (MD-390172) using the Ball Socket (MD-369777) and the Mini Level.

Technician(s) _____ Date 6/7/05

7.4 Mark the IP End Dome (MD-390172) and the End Plate with a Horizontal Witness Line. This Step will be used in Step 9.4 to reposition the Domes prior to Welding.

Technician(s) _____ Date 6 7 05

7.5 Remove the IP End Dome (MD-390172) from the Tooling.

Technician(s) _____ Date 6/7/05

7.6 Attach Non-IP End Dome (MD-390172) (Q1) to the End Dome Positioning Fixture (MD-369776).

Technician(s) _____ Date 6/7/05

7.7 Align Non-IP End Dome (MD-390172) as shown in Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 6·7·05

7.8 Level the Non-IP End Dome (MD-390172) using the Ball Socket (MD-369777) and the Mini Level.

Technician(s) _____ Date 6·7·05

7.9 Feed the Electrical wires/bus through the proper ports as the Non-IP End Dome (MD-390172) is brought into position against the End Plate.

Technician(s) _____ Date 6·7·05

7.10 Mark the Non-IP End Dome (MD-390172) and the End Plate with a Horizontal Witness Line. This Step will be used in Step 9.7 to reposition the Domes prior to Welding.

Technician(s) _____ Date 6·7·05

7.11 Remove the Non-IP End Dome (MD-390172) from the Tooling.

Technician(s) _____ Date 6/7/05

7.12 Mount the KEK Cold Mass Leveling Bracket (MD-390711) to the X side of the magnet. Record the serial number of the mini level that will be used below.

Mini Level Serial Number: #2[redacted]

Technician(s) _____ Date 6-7-05

7.13 Adjust the mini level so that it is level with respect to gravity. See the mini level instructions for this procedure.

Technician(s) _____ Date 6-7-05

7.14 Place the mini level on the leveling bracket so that the readout is facing the Non-IP end (corrector end) of the magnet. Push the level up against the leveling bracket top screws.

Record the Magnet Level here 1200.

Technician(s) _____ Date 6-7-05

7.15 Remove the mini level but leave the KEK Cold Mass Leveling Bracket (MD-390711) mounted to the Cold Mass.

Technician(s) _____ Date 6-7-05

7.16 Move the Coldmass to the Assembly Table.

Technician(s) _____ Date 6/7/05

8.0 Beam Tube Insertion

8.1 Inspect the Beam Tube (MD-369955) for damage. Clean Beam Tube using lint free Heavy Duty Wipers (Fermi stock 1660-0150) and Isopropyl Alcohol (Fermi stock 1920-0300) as per Insulated Beam Tube Assembly for Q1 (MD-369746).

O. Fria — Technician(s) — 6-15-05 — Date

8.2 Using Insertion Tooling, insert the Beam Tube (MD-369955) into the Magnet Assembly as per Beam Tube Insertion Tooling (MD-369789).

Technician(s) — 6-15-05 — Date

8.3 Position the Beam Tube (MD-369955) longitudinally per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) — 6-15-05 — Date

8.4 Place a mark 40mm from the laminations on IP End of the Beam Tube.

E. Shaw — Technician(s) — 6-15-05 — Date

8.5 Verify that the placement of the mark in Step 8.4 is correct.

Crew Chief — 6-15-05 — Date

8.6 Using the Wachs Cutter, cut the IP End of the Beam Tube at the mark.

E. Shaw / O. Fria — Technician(s) — 6-15-05 — Date

8.7 Measure the inside Beam Tube length and record this measurement below.

Step	Description	Measurement
8.7.1	**Beam Tube Length**	8068
	Subtract 7725mm (+0/-4mm)	**- 7725mm**
8.7.2	**(Length to be cut from Non-IP End)**	= 343

Technician(s) — 6-15-05 — Date

8.8 Using the number recorded in Step 8.7.2, measure and place a mark at the Non-IP End of the Beam Tube.

Technician(s) _____ Date 6-15-05

STOP

8.9 Verify that the placement of the mark in Step 8.8 is correct.

Crew Chief _____ Date 6/15/05

8.10 Using the Waehs Cutter, cut the Non-IP End of the Beam Tube at the mark.

Technician(s) _____ Date 6-15-05

8.11 Measure and verify Beam Tube length is 7725 (+0/-4mm). Record Actual Beam Tube Length below.

Actual Beam Tube Length	7725

Technician(s) _____ Date 6-15-05

STOP

Responsible Authority/Physicist _____ Date 6-15-05

8.12 Hipot the Beam Tube to coil, heaters and ground. (5kV) (Max. Leakage < 0.5μA)

STOP

Have Crew Chief verify setup and sign below before continuing.

Crew Chief — Date: 6-15-05

Hipot	Leakage or Failure Voltage	Pass	Fail
Beam Tube to coil, heaters and ground	.204 μA	✓	

Technician(s) — Date: 6-15-05

STOP

Responsible Authority/Physicist — Date: 15-JUN-2005

9.0 Dome Installation

9.1 Tack weld the Expansion Loop mounting hardware in place as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) _____ Date 6-15-05

9.2 Mount and adjust the Shipping restraint screws.

Note(s):
Weld to corrector if necessary.

Technician(s) _____ Date 6 15 05

9.4 Reposition the IP End Dome as shown in Q1 Cold Mass Welded Assembly (ME-390526) using the Horizontal Witness Line from step 7.4.

Technician(s) _____ Date 6 15 05

9.5 Tack weld the IP End Dome in place at approximately 6-8 places around the Dome per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) _____ Date 6-15-05

9.6 Weld the IP End Dome, skip weld around to minimize distortion per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) _____ Date 6-15-05

9.7 Reposition the Non-IP End Dome as shown in Q1 Cold Mass Welded Assembly (ME-390526) using the Horizontal Witness Line from step 7.10.

Technician(s) _____ Date 6-16-05

9.8 Feed the Electrical wires/Bus through the proper ports as the Non-IP End Dome is brought into position against the End Plate.

Technician(s) _____ Date 6-16-05

STOP

9.9 Ensure Spider Assemby (MC-369973) is installed properly as per Q1 Module Assembly (ME-369894).

Crew Chief — Date: 6-16-05

9.10 Tack weld the Non-IP End Dome in place at approximately 6-8 places around the Dome as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) — Date: 06/16/05

9.11 Weld the Non-IP End Dome, skip weld around to minimize distortion as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) — Date: 06/16/05

VERIFY SPIDER

6-15-05

TRR TO ADD this SIGNOFF
AFTER 9.9.
TRR#1746

10.0 Suspension System Assembly

10.1 Clean the Suspension System with Ethyl Alcohol (Fermi stock 1920-0550) and Kimwipes (Fermi stock 1660-2500) or equivalent.

Part Name	Part Number	Quantity	Completed
Fixed Support Assembly	**(ME-390041)**	**1**	✓
Sliding Support Assembly	**(ME-390042)**	**1**	✓
Tie Bar Assembly	**(ME-390400)**	**2**	✓
Tie Bar Shim, 6.4mm (.250")	**(ME-390118)**	**4**	✓
Tie Bar Shim, 2.4mm (.093")	**(ME-390119)**	**4**	✓
Tie Bar Shim, 0.8mm (.031")	**(ME-390120)**	**4**	✓
Suspension System Adjusting Screw	**(MB-390039)**	**8**	✓
M16 x 70mm SHCS	**(MA-393021)**	**8**	✓
Washer (.656" ID x 1.38" OD x .13" THK STN STEEL)	**(MA-390377)**	**8**	✓

Label the IP End and the Non-IP End of the Vacuum Vessel with a temporary sticker or equivalent.

O. Fuang
Technician(s)

6-20-05
Date

10.2 Insert the Fixed Support Assembly (ME-390041) into the Vacuum Vessel and position at the Non-IP End.

O. Fuang
Technician(s)

6-20-05
Date

10.3 Install the Suspension System Adjusting Screws (MB-390039) and Washer (MA-390377) into the Vacuum Vessel to hold the Fixed Support Assembly in place. Coat all screw threads with Molybdenum Disulfide prior to installation.



O. Friary
Technician(s)

6·20·05
Date

10.4 Adjust the Vertical and rotational alignment of the Supports using the Suspension System Adjusting Screws (MB-390039). Ensure all four screws are in contact with the Support and that Diametrically Opposing Support Lugs are equidistant from the Vacuum Vessel Wall.



O. Friary
Technician(s)

6 20 . 05
Date

10.5 Insert the Sliding Support Assembly (ME-390042) in to the Vacuum Vessel and position at the IP End.

O. Friary
Technician(s)

6·20·05
Date

10.6 Install the Suspension System Adjusting Screws (MB-390039) and Washer (MA-390377) into the Vacuum Vessel to hold the Fixed Support Assembly in place. Coat all screw threads with Molybdenum disulfide prior to installation.

[redacted]

Technician(s) _____ Date 6·20·05

10.7 Adjust the Vertical and rotational alignment of the Supports using the Suspension System Adjusting Screws (MB-390039). Ensure all four screws are in contact with the Support and that Diametrically Opposing Support Lugs are equidistant from the Vacuum Vessel Wall.



Technician(s) _____ Date 6·20·05

10.8 Assemble the Suspension System using the Fixed Support Assembly (ME-390041), the Sliding Support Assemblies (ME-390042) and the Tie Bar Assemblies (MC-390167). Insert Tie Bar Shims (MC-390118),(MB-390119) and (MB-390120) between the Sliding Support Assemblies (ME-390042) and the Tie Bar Assemblies (MC-390400) as required. (Reference drawing: ME-390525).

O. Fria _____ Technician(s) 6 20 05 _____ Date

10.9 Measure the distance between the Suspension Rings at the bottom of the Threaded Rods and record measurements below. Copy this page and place copy in designated book for later reference. (TR-333755, Q1 Cryostat Final Assembly, Step 5.1).

Non-IP North to IP North 415.5 mm

Non-IP South to IP South 415.5 mm

O. Fria _____ Technician(s) 6 20 05 _____ Date

10.10 Measure from the face of the IP end vacuum vessel flange to the inside surface of the IP end suspension system.

Record measurement here: 1298.5 mm

O. Fria _____ Technician(s) 6.20.05 _____ Date

10.11 Measure from the face of the Non-IP end vacuum vessel flange to the inside surface of the Non-IP end suspension system.

Record measurement here: 2017 mm

O. Fria _____ Technician(s) 6.20.05 _____ Date

10.12 Label the IP End Support and the Non-IP End Support. (Writing on the G-11 Support is acceptable).

O. Fria _____ Technician(s) 6 20 05 _____ Date

10.13 Loosen each Suspension System Adjusting Screw (MB-390039) 1/2 turn and remove the Suspension System from the Vacuum Vessel.

O. Fria _____ Technician(s) 6/20/05 _____ Date

10.14 Configure the Suspension Tooling for Q1 Assembly per Cryostat Layout Tooling & Assembly (ME-364604). Place Suspension Assembly on the tooling and make necessary adjustments to the tooling.

_____ Technician(s) 6.20.05 _____ Date

10.15 Assemble the Suspension Mounting Brackets (MD-390279) to the Support Assemblies.

Technician(s) _____ Date 6-21-05

10.16 Slide the Suspension System over the Cold Mass and place on tooling. The Suspension system may be disassembled during this step. Record shim sizes and locations prior to disassembly.

Note(s):

Ensure that the Suspension System is configured properly to the Cold Mass with respect to the IP and Non-IP Ends.

Technician(s) _____ Date 6-21-05

STOP

10.17 Verify locking collars exist only at Non-IP End support.

Lead Person _____ Date 6-21-05

10.18 Establish alignment between the Cold Mass and the Support system. Install shims between the Brass Slide Bars and the Stainless Steel Blocks on each support as needed.

Record Shim size and location below.

IP-North 80 mil **IP-South** 80 mil

Non-IP-North 80 mil **Non-IP-South** 80 mil

Technician(s) _____ Date 6-21-05

STOP

10.19 Verify the Alignment of the Cold Mass and the Support System.

Crew Chief _____ Date 6-21-05

10.20 Weld the Cold Mass to the Outboard Cold Mass Brackets as per (ME-390525).

Weldor(s) _____ Date 6/21/05

10.21 Weld the Shielding Blocks (MB-390534) to the Cold Mass per Q1 Suspension System Installation (ME-390525).

Weldor(s) _____ Date 6/23/05

10.22 Add 111mm to the number recorded in Step 10.10 and record below.

Recorded measurement from Step 10.10: 1298.5mm

Add: **+ 111mm**

Record New Total: 1409.5

Technician(s) _____ Date 6/22/05

10.23 Add 112.5mm to the number recorded in Step 10.11 and record below.

Recorded Measurement from Step 10.11: 2017.0

Add: **+ 112.5mm**

Record New Total: 2129.5

Technician(s) _____ Date 6/22/05

10.24 Position the IP End of the Beam Tube at the distance recorded in Step 10.22 from the inside surface of the IP G-10 support.

Technician(s) _____ Date 6/22/05

10.25 Measure the Non-IP End of the Beam Tube from the inside surface of the Non-IP End support. Compare this number to the number recorded in Step 10.23.

Note(s):

These numbers should be the same to within 1 mm. If these numbers differ greater than 1 mm, contact Responsible Authority/Physicist.

Record measurement here: 2130

Recorded measurement from Step 10.23: 2129.5

Technician(s) _____ Date 6-22-05

10.26 Measure from the IP End of the Beam Tube to the Spot Face on the IP End Dome. Record below.

Record measurement here: 27.5 mm

Technician(s) 6-22-05 Date

10.27 Subtract 15mm from the number recorded in Step 10.26. This is the Spacer width for the IP End. Record below.

Recorded Measurement from Step 10.26: 27.5

Subtract: **- 15mm**

Spacer width for the IP End: 12.5

Technician(s) 6-22-05 Date

10.28 Measure from the Non-IP End of the Beam Tube to the Spot Face on the Non-IP End Dome. Record below.

Record measurement here: 25.5

Technician(s) 6-22-05 Date

10.29 Subtract 15mm from the number recorded in Step 10.26. This is the Spacer width for the Non-IP End. Record below.

Recorded Measurement from Step 10.28: 25.5

Subtract: **- 15mm**

Spacer width for the Non-IP End: 10.5

Technician(s) 6-22-05 Date

11.0 Cold Bore

11.1 Flare both ends of the Beam Tube using Flaring Tool (MC-390416) per Q1 Cold Mass Welded Assembly (ME-390526).

O. Friang — Technician(s) — 6.23.05 — Date

11.2 Add Spacer between Beam Tube Flange and IP End Dome, if necessary.

Spacer Added? **Yes** ☑ **No** ☐

Technician(s) — 6-23-05 — Date

11.3 Position Cold Bore Flange (MC-390538) over the Beam Tube and onto IP End Dome per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) — 6-24-05 — Date

11.4 Weld the Beam Tube to the Flange at IP End as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) — 6/24/05 — Date

11.5 Position the Cold Bore Flange (MC-390538) over the Beam Tube and onto the Non-IP End Dome (Q1) per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) — 6-24-05 — Date

11.6 Weld Beam Tube to Flange at NON-IP End as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) — 6/24/05 — Date

11.7 Perform a stretched wire measurement of the system to align the Cold Mass within ± .2 mR.

Responsible Authority/Physicist — 6/26/05 — Date

11.8 Align Beam Tube and the Flange at IP End per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 6-27-05

11.9 Weld the Flange to the IP End Dome as per Q1 Cold Mass Welded Assembly (ME-390526).

Chandler Good
Weldor(s) _____ Date 6-27-05

11.10 Align Beam Tube and Flange at NON-IP End per Q1 Cold Mass Welded Assembly (ME-390526).

Technician(s) _____ Date 6-27-05

11.11 Weld the Flange to the Non-IP End Dome as per Q1 Cold Mass Welded Assembly (ME-390526).

Weldor(s) _____ Date 6/28/05

12.0 Electrical Inspection

12.1 Perform an electrical inspection on each of the Individual Quadrants and the Cold Mass. Refer to the Valhalla and Leader Free Standing Coil Measurement Procedure (ES-292306).

To measure the Resistance of a Q1 Cold Mass:

1. Use Valhalla Scientific 4300B digital micro-ohmmeter.
2. Set Test Current to 0.1 amp.
3. Set Scale to 2V full scale.
4. Turn temperature compensation on.
5. Turn test current off.
6. Connect I_{HI} to Q4 inner power lead as shown in figure.
7. Connect I_{LO} to Q3 inner power lead as shown in figure.
8. Turn test current on.
9. Connect V_{HI} and V_{LO} to voltage taps as shown in resistance table.
10. To measure Total with leads, connect V_{HI} to Q4 power lead and V_{LO} to Q3 power lead.
11. Read resistance and record in traveler.

Q1 Cold Mass Electrical Measurements



(Q1) Resistance				Nominal 3.35 to 3.45 Ω
Voltage Tap Serial Numbers				Total Resistance
Connect	Fermi	CERN	KEK	
V_{HI}	VTa1Q1	EE1111	a1	3.442 Ω
V_{LO}	VTc1Q1	EE1211	c1	
V_{HI}	VTc1Q1	EE1211	c1	3.441 Ω
V_{LO}	VTb1Q1	EE1311	b1	
V_{HI}	VTa1Q1	EE1111	a1	6.883 Ω
V_{LO}	VTb1Q1	EE1311	b1	

		Total Resistance with Leads
		Nominal 6.75 to 6.85 Ω
V_{HI}	Q4 Power Lead	6.887 Ω
V_{LO}	Q3 Power Lead	

Technician(s) _____ Date 6/22/05

Check resistance of Redundant Voltage Taps.

Q1 Redundant Voltage Taps				Nominal 3.35 to 3.45 Ω
Connect	Fermi	CERN	KEK	Resistance
V_{HI}	VTa2Q1	EE1121	a2	3.443 Ω
V_{LO}	VTc2Q1	EE1221	c2	
V_{HI}	VTc2Q1	EE1221	c2	3.443 Ω
V_{LO}	VTb2Q1	EE1321	b2	

Technician(s) _____ Date 6/22/05

To measure Ls and Q of a Q1 Cold Mass:

1. Use Agilent 4263B LCR Meter.
2. Turn power on by pushing line button. Wait 30 seconds until display screen is lit.
3. Recall program #1. To do this, push recall (Rcl), then push #1, then push Enter.
4. Push Auto/Hold button to release hold.
5. Verify that the frequency displayed in the upper right corner of the display screen is 1000 Hz and the level recorded in the lower right corner of the display screen is 1V or 1000 mV.
6. Connect H_{cur} to Quadrant 4 power lead as shown in figure.
7. Connect L_{cur} to Quadrant 3 power lead as shown in figure.
8. Connect H_{pot} and L_{pot} buttons to voltage taps as shown below.

To measure Q1:

- To measure Quadrants 1&4, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTc1 (EE1211 for Q1).
- To measure Quadrants 2&3, connect H_{pot} to VTc1 (EE1211 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).
- To measure total, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).

9. Read Ls and Q from display and record in traveler.



(Q1) Inductance				Nominal 15 to 16 mH
Voltage Tap Serial Numbers				Total Inductance
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	15.727 mH
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	15.643 mH
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 30 to 32 mH
				Total Inductance
H_{POT}	VTa1Q1	EE1111	a1	31.372 mH
L_{POT}	VTb1Q1	EE1311	b1	

(Q1) Q-Factor				Nominal 1.0 to 1.2
Voltage Tap Serial Numbers				Total Q
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	1.2
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	1.2
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 1.0 to 1.2
				Total Q
H_{POT}	VTa1Q1	EE1111	a1	1.2
L_{POT}	VTb1Q1	EE1311	b1	

Technician(s)

6/22/05
Date

To measure the resistance of a Thermometer (RTD):

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
   U+ (Black) to Sense HI
   I+ (Yellow) to Input HI
   U- (Red) to Sense LO
   I- (Green) to Input LO
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
8. Read resistance in ohms and record in traveler.



To measure the resistance of a Cryogenic (Warm-up) Heater

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
   Note: Although this is technically a 4 wire measurement, it is effectively a 2 wire measurement, since there are only 2 wires connected to each heater.
8. Read resistance in ohms and record in traveler.



Q1 - RTD's and Cryogenic (warm-up) Heaters				
Temperature of Building (± 5°): 70° F				
Component	**Fermi**	**CERN**	**Range**	**Resistance**
Q1 RTD, primary	TaQ1	TT8311	60 to 70 Ω	73.531 Ω
Q1 RTD, redundant	TbQ1	TT8321	60 to 70 Ω	67.729 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at top (CERN #1 I+)	W1aQ1	EH8311+	16 to 18.5 Ω	16.1875 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at bottom (CERN #1 I-)	W2aQ1	EH8311-		
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at top (CERN #2 I+)	W1bQ1	EH8321+	16 to 18.5 Ω	16.475 Ω
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at bottom (CERN #2 I-)	W2bQ1	EH8321-		

Technician(s) _____ Date 6/22/05

Using the Hewlett Packard HP3457A digital multimeter, measure the Protection (Strip) Heater Resistance for Q1.

Q1 Protection (Strip) Heater Resistance					
Fermi	**CERN**	**KEK**	**Description**	**Limit**	**Resistance**
H1aQ1	YT1111+	HA1	Circuit A	28 to 32 Ω	28.813 Ω
H2aQ1	YT1111-	HA2			
H1bQ1	YT1121+	HB1	Circuit B	28 to 32 Ω	28.863 Ω
H2bQ1	YT1121-	HB2			

Technician(s) _____ Date 6/22/05

DR 4265

12.2 Using the HP4284A, connect power thru the corrector Power Leads (H1A and H1B to measure Q1-H1 or V1A and V1B to measure Q1-V1). Connect the Sense Leads as shown in table below and record resistance.

Corrector Bus Leads

	V1A	V1B	H1A	H1B

(View Looking into Q1)

Readout Labels		Power Labels	Resistance
V1A	EE8111	V1A, V1B	.025 Ω
EE8111	V1B		17.7014 Ω
V1A	V1B		17.702 Ω
H1A	EE8121	H1A, H1B	.002 Ω
EE8121	H1B		21.61 Ω
H1A	H1B		21.676 Ω

Technician(s) _____ Date 6/22/05

12.3 Hipot according to table below. Hipot to 3kV. Maximum leakage is 3μA.

STOP

Have Crew Chief verify setup and sign below before continuing.

Crew Chief

6-22-05
Date

Hipot Heaters to Coil and Ground.

High Potential	Grounded	Floating	Leakage
All Strip Heaters	Coils, Yoke, Q1 Instrumentation Bus, Lead and Corrector Coil Busses, RTD's and Warm-up Heaters	Nothing	648 nA

Hipot Coil to Heaters and Ground.

High Potential	Grounded	Floating	Leakage
All Coils	Strip Heaters, Yoke, Q1 Instrumentation Bus, 8kA and 5kA Lead Busses and Corrector Coil Busses, RTD's and Warm-up Heaters	Nothing	192 nA

Technician(s)

6/22/05
Date

STOP

Responsible Authority/Physicist

JOI-JUN-2005
Date

13.0 Installation of Hypertronics

DR# 4267

13.1 Assemble/Install Hypertronics Connectors, **without Cover** at **Non-IP End** as per Q1 Module Assembly (ME-369894). Pin Numbers for connectors are shown in Table 13.1 below

Table 13.1

Module	Pin	Fermilab Label	CERN Label	KEK Label	Description
M1	1				Blank Module
M1	2				
M1	3				
M1	4				
M1	5				
M2	1	VTa1Q1	EE1111	a1	Q1 Lead Voltage Tap "a", primary
M2	2	VTa2Q1	EE1121	a2	Q1 Lead Voltage Tap "a",redundant
M2	3	VTc1Q1	EE1211	c1	Q1 Center Voltage Tap "c", primary
M2	4	VTc2Q1	EE1221	c2	Q1 Center Voltage Tap "c", redundant
M2	5	VTb1Q1	EE1311	b1	Q1 Lead Voltage Tap "b", primary
M3	1	Empty	Empty		No Connection
M3	2	Empty	Empty		No Connection
M3	3	Empty	Empty		No Connection
M3	4	Empty	Empty		No Connection
M3	5	VTb2Q1	EE1321	b2	Q1 Lead Voltage Tap "b",redundant
M4	1				Blank Module
M4	2				
M4	3				
M4	4				
M4	5				
M5	1	VTH1	EE8121		Corrector voltage tap Q1-H1 (skew dipole) (on MCBX, MCBXH, A+ lead)
M5	2	VTV1	EE8111		Corrector voltage tap Q1-V1 (normal dipole) (on MCBX, MCBXV A+ lead)
M5	3	Empty	Empty		No Connection
M5	4	Empty	Empty		No Connection
M5	5	Empty	Empty		No Connection
M6	1				Blank Module
M6	2				
M6	3				
M6	4				
M6	5				
M7	1	W1aQ1	EH8311+		Q1 Cryogenic Heater lead end - wire at top (CERN #1 I+)
M7	2	W2aQ1	EH8311-		Q1 Cryogenic Heater lead end - wire at bottom (CERN #1 I-)
M7	3	W1bQ1	EH8321+		Q1 Cryogenic Heater non-lead end - wire at top (CERN #2 I+)
M7	4	W2bQ1	EH8321-		Q1 Cryogenic Heater non-lead end - wire at bottom (CERN #2 I-)
M7	5	Empty	Empty		No Connection

Table 13.1 (continued)

Module	Pin	Fermilab Label	CERN Label	KEK Label	Description
M8	1	Blank			Blank Module
M8	2	Blank			
M8	3	Blank			
M8	4	Blank			
M8	5	Blank			
M9	1	H1aQ1	YT1111+	HA1	Q1 Protection (Strip) Heater, ("a" circuit) (CERN lead #1+)
M9	2	Empty	Empty		No connection
M9	3	H2aQ1	YT1111-	HA2	Q1Protection (Strip) Heater, ("a" circuit) (CERN lead #1-)
M9	4	Empty	Empty		No connection
M9	5	H1bQ1	YT1121+	HB1	Q1 Protection (Strip) Heater, ("b" circuit) (CERN lead #2+)
M10	1	Empty	Empty		No connection
M10	2	Empty	Empty		No connection
M10	3	Empty	Empty		No connection
M10	4	H2bQ1	YT1121-	HB2	Q1 Protection (Strip) Heater, ("b" circuit) (CERN lead #2-)
M10	5	Empty	Empty		No connection
M11	1				Blank Module
M11	2				
M11	3				
M11	4				
M11	5				
Note: Pin Numbers of Module M12 are not listed in numerical order.					
M12	1	TaQ1_I+	TT8311 I+		Q1 RTD, primary Wire color: Yellow
M12	2	TaQ1_I-	TT8311 I-		Q1 RTD, primary Wire color: Green
M12	3	TaQ1_V+	TT8311 U+		Q1 RTD, primary Wire color: Black
M12	4	TaQ1_V-	TT8311 U-		Q1 RTD, primary Wire color: Red
M12	5	TbQ1_I+	TT8321 I+		Q1 RTD, redundant: Wire color: Yellow
M12	6	TbQ1_I-	TT8321 I-		Q1 RTD, redundant: Wire color: Green
M12	11	TbQ1_V+	TT8321 U+		Q1 RTD, redundant: Wire color: Black
M12	10	TbQ1_V-	TT8321 U-		Q1 RTD, redundant: Wire color: Red
M12	9	Empty	Empty		No connection
M12	8	Empty	Empty		No connection
M12	7	Empty	Empty		No connection
M12	12	Empty	Empty		No connection
M12	13	Empty	Empty		No connection
M12	14	Empty	Empty		No connection
M12	15	Empty	Empty		No connection
M12	16	Empty	Empty		No connection
M12	17	Empty	Empty		No connection

Hypertronics Connector Pin Locations (Q1 non-ip end)

VIEW: Male (pin) solder cup side



- ● Hole filled in grey: Wire soldered to pin.
- ⊙ Hole with dot in center: Pin exists but no wire soldered to it.
- ○ Hole filled in white: No pin. Hole is drilled out.



Note(s):

Ensure the Hypertronics cover has NOT been installed.

Technician(s) _____ Date 7/05/2005

13.2 Inspect Hypertronics Connector. Ensure that it is free of flux and that Kapton has been installed properly.

Responsible Authority/Physicist _____ Date 29-JUN-2005

13.3 After LHC Project Physicist / designee has signed the above step, complete the installation of the Hypertronics.

Technician(s) _____ Date 7/05/2005

After re-work _____ 6-JUL-2005

14.0 Final Electrical Inspection

14.1 Perform an electrical inspection on each of the Individual Quadrants and the Cold Mass. Refer to the Valhalla and Leader Free Standing Coil Measurement Procedure (ES-292306).

To measure the Resistance of a Q1 Cold Mass:

1. Use Valhalla Scientific 4300B digital micro-ohmmeter.
2. Set Test Current to 0.1 amp.
3. Set Scale to 2V full scale.
4. Turn temperature compensation on.
5. Turn test current off.
6. Connect I_{HI} to Q4 inner power lead as shown in figure.
7. Connect I_{LO} to Q3 inner power lead as shown in figure.
8. Turn test current on.
9. Connect V_{HI} and V_{LO} to voltage taps as shown in resistance table.
10. To measure Total with leads, connect V_{HI} to Q4 power lead and V_{LO} to Q3 power lead.
11. Read resistance and record in traveler.

Q1 Cold Mass Electrical Measurements



(Q1) Resistance				Nominal 3.35 to 3.45 Ω
Voltage Tap Serial Numbers				Total Resistance
Connect	Fermi	CERN	KEK	
V_{HI}	VTa1Q1	EE1111	a1	3.42 Ω
V_{LO}	VTc1Q1	EE1211	c1	
V_{HI}	VTc1Q1	EE1211	c1	3.42 Ω
V_{LO}	VTb1Q1	EE1311	b1	
V_{HI}	VTa1Q1	EE1111	a1	6.84 Ω
V_{LO}	VTb1Q1	EE1311	b1	

Technician(s) 7/6/05 Date

Check resistance of Redundant Voltage Taps.

Q1 Redundant Voltage Taps				Nominal 3.35 to 3.45 Ω
Connect	Fermi	CERN	KEK	Resistance
V_{HI}	VTa2Q1	EE1121	a2	3.42 Ω
V_{LO}	VTc2Q1	EE1221	c2	
V_{HI}	VTc2Q1	EE1221	c2	3.42 Ω
V_{LO}	VTb2Q1	EE1321	b2	

Technician(s) 7/6/05 Date

To measure Ls and Q of a Q1 Cold Mass:

1. Use Agilent 4263B LCR Meter.
2. Turn power on by pushing line button. Wait 30 seconds until display screen is lit.
3. Recall program #1. To do this, push recall (Rcl), then push #1, then push Enter.
4. Push Auto/Hold button to release hold.
5. Verify that the frequency displayed in the upper right corner of the display screen is 1000 Hz and the level recorded in the lower right corner of the display screen is 1V or 1000 mV.
6. Connect H_{cur} to Quadrant 4 power lead as shown in figure.
7. Connect L_{cur} to Quadrant 3 power lead as shown in figure.
8. Connect H_{pot} and L_{pot} buttons to voltage taps as shown below.

To measure Q1:

- To measure Quadrants 1&4, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTc1 (EE1211 for Q1).
- To measure Quadrants 2&3, connect H_{pot} to VTc1 (EE1211 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).
- To measure total, connect H_{pot} to VTa1 (EE1111 for Q1), and L_{pot} to VTb1 (EE1311 for Q1).

9. Read Ls and Q from display and record in traveler.



(Q1) Inductance				Nominal 15 to 16 mH
Voltage Tap Serial Numbers				Total Inductance
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	15.49 mH
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	15.47 mH
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 30 to 32 mH
				Total Inductance
H_{POT}	VTa1Q1	EE1111	a1	30.95 mH
L_{POT}	VTb1Q1	EE1311	b1	

(Q1) Q-Factor				Nominal 1.0 to 1.2
Voltage Tap Serial Numbers				Total Q
Connect	Fermi	CERN	KEK	
H_{POT}	VTa1Q1	EE1111	a1	1.1
L_{POT}	VTc1Q1	EE1211	c1	
H_{POT}	VTc1Q1	EE1211	c1	1.1
L_{POT}	VTb1Q1	EE1311	b1	

				Nominal 1.0 to 1.2
				Total Q
H_{POT}	VTa1Q1	EE1111	a1	1.1
L_{POT}	VTb1Q1	EE1311	b1	

Technician(s) [signature]

Date 7/6/05

To measure the resistance of a Thermometer (RTD):

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
   U+ (Black) to Sense HI
   I+ (Yellow) to Input HI
   U- (Red) to Sense LO
   I- (Green) to Input LO
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
8. Read resistance in ohms and record in traveler.



To measure the resistance of a Cryogenic (Warm-up) Heater

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
   Note: Although this is technically a 4 wire measurement, it is effectively a 2 wire measurement, since there are only 2 wires connected to each heater.
8. Read resistance in ohms and record in traveler.



14.2 Hipot according to table below. Hipot to 3kV. Maximum leakage is 3μA.

STOP

Have Crew Chief verify setup and sign below before continuing.

Crew Chief

7.6.05
Date

Hipot Heaters to Coil and Ground.

High Potential	Grounded	Floating	Leakage
All Strip Heaters	Coils, Yoke, Q1 Instrumentation Bus, Lead and Corrector Coil Busses, RTD's and Warm-up Heaters	Nothing	237na

Hipot Coil to Heaters and Ground.

High Potential	Grounded	Floating	Leakage
All Coils	Strip Heaters, Yoke, Q1 Instrumentation Bus, 8kA and 5kA Lead Busses and Corrector Coil Busses, RTD's and Warm-up Heaters	Nothing	372na

Technician(s)

7-6-05
Date

STOP

Responsible Authority/Physicist

7-JUL-2005
Date

STOP

14.3 Ensure electrical measurements are acceptable and confirm Hypertronics Connector has been installed properly.

Responsible Authority/Physicist

7-JUL-2005
Date

15.0 Production Complete

15.1 Process Engineering verify that the Q1 Cold Mass Module Assembly Traveler (5520-TR-333754) is accurate and complete. This shall include a review of all steps to ensure that all operations have been completed and signed off. Ensure that all Discrepancy Reports, Nonconformance Reports, Repair/Rework Forms, Deviation Index and dispositions have been reviewed by the Responsible Authority for conformance before being approved.

Comments:

_____

_____

_____

_____

_____

_____

Process Engineering/Designee

SEP 19 2005
Date

TD - Engineering Fabri ion Component Kit List

ORIGIN

Process Engineering

Component Serial No. LMQXA08

Kit submitted by: John Szostak | Ext. 2003

Fermi ID No. 02943C

Date submitted: 7-Mar-05

Need date: 15-Mar-05

Deliver to: ICB

Use with Traveler No. 333754

Job No. 248

M&S task number: 300 | 1.1.1.3.4

Drawing Title: **Q1 MODULE ASSEMBLY - FINAL ASSEMBLY**

Drawing No. **ME-369894** | **Rev. C**

Drawing Title: **Q1 COLD MASS WELDED ASSEMBLY**

Drawing No. **ME-390526** | **Rev. D**

Material Control

Parts available

Verified by: M. Schmidt (MS)

Fermi ID No. 04223N

Date submitted to stockroom: 10-Mar-05

Parts issued

Issued by: P. Mu

Fermi ID No. 12792

Date issued: 3-11-05

Parts received by E&F: J. Szostak

Fermi ID No. 02943C

Date received by E&F: 3/11/05

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
1	26 GAUGE WIRE EXTNS (For Voltage Taps)	MA	369832	*		MTF HAS					
2	20 GAUGE WIRE EXTNS (For Strip & Warmup Heaters)	MA	369833	*		MTF HAS					
3	WARMUP HEATER	MA	369834	A	EA	2	IB4 Bin	2	JSA	79919	63 pcs.
4	RTD ASSEMBLY	MA	369835	A	EA	2	R2,S2,L5	2	JSA	79920	20 pcs.
5	RTD MOUNTING BLOCK	MA	369893	B	EA	2	IB4 Bin	2	JSA	80543	18 pcs.
6	.010" SOLDER STRIP	MA	369904	*	METER	ICB HAS					
7	KESTER 135 FLUX	MA	369911	*		A / R					
8	KEVLAR STRING	MA	369912	*		A / R					
9	LINEAR CABLE CLAMP CAP Q1 / Q3	MB	369922	A	EA	1	IB4 Bin	1	JSA	81468	11 pcs.

ORIGINAL

TD - Engineering Fabri ion Component Kit List

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
10	SHCS, #4-40 x 1/4 LG. STN STEEL	MA	369938	*	EA	4	IB4 Bin	4		79032	96 pcs.
11	LEAD BUS EXIT SUPPORT	MC	369951	B	EA	1	IB4 Bin	1		81386	3 pcs.
12	LEAD SPLICE HOUSING	MD	369952	A	EA	1	IB4 Bin	1		81387	3 pcs.
13	LEAD SPLICE HOUSING COVER	MC	369953	*	EA	1	IB4 Bin	1		80809	3 pcs.
14	EXPANSION LOOP ASSEMBLY	MB	369962	*		ICB HAS					
15	LINEAR CABLE CLAMP ENCLOSER Q1	MB	369963	*	EA	1	IB4 Bin	1		81568	2 pcs.
16	Q1 / Q3 WARMUP HEATER BASE PLATE	MB	369997	A	EA	2	IB4 Bin	2		80090	16 pcs.
17	MCBX CORRECTOR MOUNTING RING	ME	390037	C	EA	1	P/N	1		80790	9 pcs.
18	LQXA COLD MASS ASSEMBLY	ME	390108	E		ICB HAS					
19	SCREW, FLAT HEAD SOCKET, M12 x 1.75 x 20mm LG S.S.	MA	393291	*	EA	2	IB4 Bin	2		80694	86 pcs.
20	IP END DOME WELDMENT	MD	390172	C	EA	1	P/N	1		78160	3 pcs.
21	MCBX CORRECTOR MOUNTING FLAT WASHER	MB	390228	*	EA	4	IB4 Bin	4			~~9 pcs.~~
22	SCREW FOR Q1/Q2 MCBX - 3.0" LG SILVER PLATED	MA	390247	*	EA	4	IB4 Bin	4		74622	55 pcs.
23	NON-IP END DOME WELDMENT	MD	390255	A	EA	1	P/N	1		78843	~~2 pcs.~~
24	TRANSPORT RESTRAINT ADJ. SCREW	MB	390270	A	EA	4	IB4 Bin	4		76665	40 pcs.
25	MCBX CORRECTOR MAGNET WELDMENT	MD	390312	*		ICB HAS					
26	MCBX CORRECTOR TRANSPORT. RESTRAINT NUT (ON DWG MD-391312)	MC	390294	*	EA	4	IB4 Bin	4		76666	32 pcs.
27	SHIM, .05 (.002")	MA	390482	*	EA	4	R2,S2,L4	4		79123	77 pcs.

ORIGINAL

TD - Engineering Fabri ion Component Kit List

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
28	SHIM, .13 (.005")	MA	390483	*	EA	4	R2,S2,L4	4	✓	79124	84 pcs.
29	SHIM, .25 (.010")	MA	390484	*	EA	4	R2,S2,L4	4	✓	79125	67 pcs.
30	SHIM, .38 (.015")	MA	390485	*	EA	4	R2,S2,L4	4	✓	79126	55 pcs.
31	BEAM TUBE FLANGE	MC	390538	*	EA	2	IB4 Bin	2	[illegible]	79332	4 pcs.
32	FACE PLATE FOR CORRECTION LEADS	MD	390734	B	EA	1	R1,3,2	1	[illegible]	81757	2 pcs.
33	Q1 (&Q3) COLD MASS FIDUCIAL MOUNTING BLOCK	MA	390808	*	EA	2	R1,1,3	2	[illegible]	82260	18 pcs.
34	NO. 10-32UNF x 4.78 (.188") LG CAP POINT SET SCREW; 18-8 SS	MA	393030	*	EA	8	IB4 Bin	8	[illegible]	82379	170 pcs.
35	SHCS (FOR RTD ASSEMBLY)	MA	393180	*	EA	4	IB4 Bin	4	[illegible]	79631	679 pcs.
36	WASHER (FOR RTD ASSEMBLY)	MA	393181	*	EA	4	IB4 Bin	4	[illegible]	81827	124 pcs.
37	SHCS, 5/16 - 18 UNC - 2A x 1.00 LG. S.S.	MA	393263	*	EA	2	IB4 Bin				RF 82970
38	SHCS, 1/4-20 UNC x .75 LG S.S. (For Splice Housing)	MA	393290	*	EA	8	IB4 Bin	8	[illegible]	80709	52 pcs.
39	SCREW, FL. HD. SOCKET M12 x 1.75 x 20mm LG. S.S.	MA	393291	*	EA	4	IB4 Bin	4	[illegible]	80694	86 pcs.
40	EXPANSION LOOP BUS SPLINE	MD	430053	*		ICB HAS					
41	INSTRUMENTATION BUS SUPPORT SLEEVE	MB	430054	*	EA	2	IB4 Bin	2	[illegible]	80804	9 pcs.
42	BACKING SPLINE - EXIT TO SPIDER	MB	430058	*	EA	2	R2,2,3	2	[illegible]	81103	9 pcs.

ORIGINA

TD - Engineering Fabri ion Component Kit List

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
Q1 INSTRUMENTATION WIRE FEEDTHRU ASSY		MB	430008	A	EA	(1)					
43	**WIRE FEED-THRU TUBE**	**MB**	**369827**	**A**	**EA**	**3**	**R1,2,4**	3			**36 pcs.**
44	**SLEEVE - INST. WIRE TUBE**	**MB**	**369996**	**A**	**EA**	**3**	**IB4 Bin**	3		80057	**64 pcs.**
45	**INSTRUMENTATION WIRE BUS**	**MB**	**369998**	*		**ICB HAS**					
46	**ANCHOR - INSTRUMENTATION TUBE**	**MB**	**430009**	*	**EA**	**1**	**IB4 Bin**	1		80811	**10 pcs.**
47	**END INSTRUMENTATION WIRE TUBE**	**MB**	**430011**	*	**EA**	**1**	**R1,S2,L3**	1		82516	**11 pcs.**
Q1 EXPANSION LOOP STABILIZER ASSEMBLY		ME	430039	A	EA	(1)					
48	**SHCS, 1/4-20 UNC-2A x .50 LG. S.S.**	**MA**	**393179**	*	**EA**	**4**	**IB4 Bin**	4		79629	**75 pcs.**
49	**SHCS, #10-32 UNF-2A x .50 LG. S.S.**	**MA**	**393280**	*	**EA**	**2**	**IB4 Bin**	2		81066	**188 pcs.**
50	**SHCS, #10-32 UNF-2A x 1.00 LG. S.S.**	**MA**	**393281**	*	**EA**	**4**	**IB4 Bin**	4		81067	**176 pcs.**
51	**SHCS, #10-32 UNF-2A x 1.25 LG. S.S.**	**MA**	**393282**	*	**EA**	**4**	**IB4 Bin**	4		81068	**168 pcs.**
52	**NUT, HEX #10-32 UNF- 2B S.S.**	**MA**	**393283**	*	**EA**	**8**	**IB4 Bin**	8		81069	**148 pcs.**
53	**STABILIZER SUPPORT**	**MC**	**430007**	*	**EA**	**2**	**R2,S2,L4**	2		80987	**29 pcs.**
54	**STABILIZER BRACKET**	**MB**	**430010**	**A**	**EA**	**2**	**R2,2,4**	2		80988	**32 pcs.**
55	**EXPANSION LOOP STABILIZER MOUNT**	**MD**	**430012**	**A**	**EA**	**1**	**R7,2,4**	1		80944	**3 pcs.**
56	**HEATER WIRE HOLD DOWN CLIP**	**MB**	**430015**	**A**	**EA**	**2**	**R2,2,4**	2		81758	**49 pcs.**
57	**SLEEVE, G-11 x .25 LG**	**MB**	**430048**	*	**EA**	**8**	**IB4 Bin**	8		80990	**36 pcs.**

ORIGINAL

TD - Engineering Fabri ion Component Kit List

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
Q1 EXPANSION LOOP LINEAR CABLE CLAMP ASSY.		MD	430040	A	EA	(1)					
58	**LINEAR CLAMP SLIDE**	**MC**	**369924**	**D**	**EA**	**1**	**R1,S3,L2**	1		80926	**11 pcs.**
59	**LINEAR CLAMP BASE MOUNT**	**MC**	**369925**	**E**	**EA**	**1**	**R1,S3,L2**	1		81542	**11 pcs.**
60	**LINEAR CLAMP BASE BLOCK**	**MD**	**369926**	**C**	**EA**	**1**	**R7,2,4**	1		80940	**11 pcs.**
61	**SHCS 3/8-16 UNC-2A x 1.00 LG S.S.**	**MA**	**393292**	*****	**EA**	**2**	**IB4 Bin**	2		81393	**92 pcs.**
Q1 LEAD END SPIDER ASSY.		MB	430042	B	EA	(1)					
62	**SHCS, #8-32 UNC-2A x .75 LG S.S.**	**MA**	**393071**	*****	**EA**	**4**	**IB4 Bin**	4		81430	**68 pcs.**
63	**SHCS, #6-32 UNC-2A x 1.00 LG S.S.**	**MA**	**393082**	*****	**EA**	**2**	**IB4 Bin**	2		81360	**74 pcs.**
64	**WASHER , NARROW FLAT #6 S.S.**	**MA**	**393088**	*****	**EA**	**2**	**IB4 Bin**	2		81361	**454 pcs.**
65	**HEX NUT, 6-32 UNC-2A S.S.**	**MA**	**393089**	*****	**EA**	**2**	**IB4 Bin**	2		82599	**150 pcs.**
66	**HEX NUT, 8-32 UNC-2A S.S.**	**MA**	**393275**	*****	**EA**	**3**	**IB4 Bin**	3		81438	**43 pcs.**
67	**SHCS, #8-32 UNC-2A x 1.25 LG S.S.**	**MA**	**393317**	*****	**EA**	**3**	**IB4 Bin**	3		81364	**79 pcs.**
68	**WASHER, NARROW FLAT, #8 S.S.**	**MA**	**393318**	*****	**EA**	**3**	**IB4 Bin**	3		81363	**235 pcs.**
69	**BUS SPIDER HOUSING ASSEMBLY**	**MD**	**430044**	**C**	**EA**	**1**	**IB4 Bin**	1		81469	**15 pcs.**
70	**BUS SPIDER HOUSING BOTTOM**	**MB**	**430055**	**B**	**EA**	**1**	**IB4 Bin**	1		82766	**7 pcs.**
71	**BUS SPIDER HOUSING TOP COVER**	**MB**	**430056**	*****	**EA**	**1**	**IB4 Bin**	1		81610	**12 pcs.**
72	**BACKING SPLINE - CORRECTOR WIRE LOOP**	**MC**	**430069**	*****	**EA**	**1**					**ICB to make**
73	**CORRECTOR WIRE SUPPORT**	**MC**	**430070**	**A**	**EA**	**1**	**IB4 Bin**	1		81397	**3 pcs.**

TD - Engineering Fabr tion Component Kit List ORIGINAL

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
74	CORRECTOR WIRE CLAMP	MB	430071	A	EA	1	IB4 Bin	1	✓	81396	3 pcs.
75	SPIDER BUMPER	MB	430075	*	EA	2	IB4 Bin	2	✓	81447	122 pcs.
INSULATED BEAM TUBE		MD	369955	A	EA	(1)	ICB has				
74	1 MIL KAPTON W/ POLYMIDE ADHESIVE	MA	369840	A		A / R					
75	2 MIL KAPTON W/ POLYMIDE ADHESIVE	MA	369841	A		A / R					
76	Q1 BEAM TUBE	MC	369954	*		ICB HAS					
77	Q1 ABSORBER LAMINATIONS	MC	390670	*		ICB HAS					
Q1 HYPERTRONICS CONNECTOR ASSEMBLY		MB	418119	*	EA	(1)					Place part #'s 75-84 in one bag and label as MB-418119
? 78	13 UNIT CONNECTOR	MA	418067	A	EA	1					IB1 to supply
79	TIE DOWN LINK	MA	418109	A	EA	4	R1,1,2	4	✓	N/A	45 pcs.
80	CLAMPING BAR	MA	418112	*	EA	1	IB4 Bin	1	✓	79990	15 pcs.
81	GROMMET	MA	418113	*	EA	1	IB4 Bin	1	✓	N/A	14 pcs.
82	M3 THRD. STUD. ASSEMBLY	MA	418114	*	EA	4	IB4 Bin	4	✓	81575	71 pcs.
83	SCREW 6-32 X 3/8" LG	MA	418116	*	EA	4	R1,1,2	4	✓	79892	48 pcs.
84	SCREW 4-40 X 1/2" TO FLANGE	MA	418117	*	EA	4	R1,1,2	4	✓	79891	120 pcs.
85	SUPPORT ARM WELDMENT - 13	MA	418125	*	Pair	1	IB4 Bin	1	✓	80121	2 pcs.
86	13 UNIT MALE PIN RACK	MA	418137	A	EA	1	R1,S1,L2	1	✓	N/A	1 pc.
87	ANTI-ARC KAPTON	MA	418143	*	EA	10	R1,1,2	10	✓	N/A	1253 pcs.

Revision Request Control Number: 1746

Specification Number: 5520 - TR - 333754 Current Revision: F

Traveler or Document Title LHC Q1 LMQXA Cold Mass Module Assembly Traveler

Step #/Description of Revision:

4.6	Added Step. "Attach the Leveling Fixture to the side of the Cold Mass. Adjust the Mini-Level to "level" (Gravity) and rotate the Cold Mass to "level"."
4.7	Added Step. Install Crossbars (MX-XXXXXX). ""
4.11	Modified Step. Added underlined "Using Corrector Coil Leveling Fixture and Mini-Level, position and align the MCBX Correction Coil (MD-390312)."
5.11	Modified Step. Changed Part No. (MA-360007) to (MA-369997) per LMQXA05.
5.11	Added Step. "Install Bus Tube Flanges (MX-XXXXXX)."
5.12	Added Step. "Tack Weld the Bus Tube Flanges (MX-XXXXXX)."
5.16	Added Step. "Hipot Cryogenic (Warm-up) Heaters to 300V. Use Droege Serial No. 910 (FNAL Part No. 51330) or equivalent. (Max. Leakage < 0.1 □A)" (Was part of 5.15)
6.1	Modified Step. In Resistance Table, move the a1 and b1 (KEK) rows down to the correct nominal resistance area. Added column for RTD's for Manufacturer's Resistance (Expedition), per Damon Bice.
7.4	Added Step. "Verify that the IP End Dome (MD-390172) is oriented properly before continuing." Per DR No. 4260.
7.7	Removed Step. Combined with Step 7.10. Per Damon Bice. New Step 7.9.
7.11	Added Step. "Verify that the Non-IP End Dome (MD-390172) is oriented properly before continuing." Per DR No. 4260.
7.13	Modified Step. Changed to "Mount the KEK Cold Mass Leveling Bracket (MD-390711) to the *X side of the magnet. (*The bracket can be mounted to either side, as long as it remains or is remounted to the same location when used later in the traveler.) Record the serial number of the mini level that will be used, below."
7.15	Added Step. "Perform preliminary reference measurements before moving the Cold Mass to an Assembly Table. Check one (Upper / Lower slash) and then record the reference measurement and Mini-level No. Take measurement while looking from Non-Lead End toward the Lead End."
8.2	Added Step. "Prepare Beam Tube (MD-369955) for insertion. (Use Kapton tape where necessary.)" per Damon Bice.
9.2	Modified Step. Changed to "Mark / Layout and adjust the Shipping restraint screws."
9.3	Added Step. "Weld the Shipping Restraint Screws to the Corrector."
9.6	Removed Step. Combined with New Step 9.7.
10.3	Modified Step. Clarified "Fixed" Support at Non-IP End
10.4	Modified Step. Clarified "Fixed" Support at Non-IP End

John Szostak	Jim Rife	6/3/2005
Originator	Responsible Authority	Date

Revision Incorporated into the Traveler:

Revision Incorporated By	Date

Process Engineering Final Review:

Process Engineering/Designee	Date

Instructions for the completion of the Revision Request Form

Note(s):

Multiple steps may be effected by one Revision Request Form but only one specific Traveler or Document may be effected by each Revision Request Form.

If completing this form by hand, a Revision Request Control Number must be obtained before processing.

If completing this form entirely by electronic means, the printed copy to be filed in the Process Engineering Office is to be initialed by the individual incorporating the Revision Request and the individual who reviewed the Traveler or Document.

Originator Instructions:

1) Specification Number: - Enter the Specification Number of the Traveler or Document to be revised. (Document title is inserted automatically from the spec. #)

2) Current Revision: - Enter the Revision of the Traveler or Document to be revised.

3) Step# / Description of the Revision: - Enter a description of the revision to be made and the step# it applies to, if applicable. If needed to describe the revision attach a copy of the page(s). If the revision is coming from a related document such as a Discrepancy Report or an Engineering Order attach a copy of that document to the Revision Request Form.

4) Originator: - Originator is the person generating the form. (Select Name from List)

5) Responsible Authority: - Responsible Authority is person responsible for the process in question. (Select Name from List)

Process Engineering Office Instructions:

1) Revision Incorporated into the Traveler: - Signature of the individual who incorporated the revision.

2) Process Engineering Final Review: - Review the Traveler or Document revised, sign and date the form. The original completed Revision Request Form will be retained by the Process Engineering Office in the Revision Request Binder.

Traveler Title:	Specification No:	Revision:	DR No:
LHC Q1 LMQXA Cold Mass Module Assembly Traveler	333754	F	4205

Step No:	Drawing No:	Routing Form No:	Serial No:	Rework ID:
4.4	ME-390526		LMQXA08	0

Discrepancy Description:

Coldmass MQXBA09 was received with an RTD block welded in the Non-Lead End, instrumentation bus side port. This welded block had an RTD attatched to it upon receipt at Fermilab.

Originator: Damon Bice

Date: 5/20/2005

Cause of Nonconformance:

Manufacturer forgot to remove the block before shipping.

Responsible Authority: Rodger Bossert

Date: 8/9/2005 8:37:12 AM

Disposition:

This extra block has no effect on magnet performance. Remove RTD from block and leave block on magnet.

Responsible Authority: Rodger Bossert

Date: 8/9/2005

Corrective Action to Prevent Recurrence:

None Required. All magnets have already been delivered. If this happens in the future, simply remove the RTD and leave the block. No Traveler Change.

Responsible Authority: Rodger Bossert

Date: 8/9/2005

Corrective Action/Disposition Verified By: John Szostak

Date: 8/31/2005 10:23:54 AM

Will Configuration be affected?: ☐ YES ☑ NO

Identified problem area:

☑ Material ☐ Manpower ☐ Method ☐ Machine ☐ Measurement

Reviewed By: Bob Jensen

Date: 9/1/2005

Traveler Title:	Specification No:	Revision:	DR No:
LHC Q1 LMQXA Cold Mass Module Assembly Traveler	333754	F	4257

Step No:	Drawing No:	Routing Form No:	Serial No:	Rework ID:
5.27	369894		LMQXA08	0

Discrepancy Description:

During preparation of the corrector leads for soldering, the V1B corrector lead broke off.

Originator: Damon Bice

Date: 6/8/2005 11:06:12 AM

Cause of Nonconformance:

V1B corrector lead weakened somehow (due to handling?) causing it to break off at lead extender splice block.

Responsible Authority: Andy Hocker

Date: 6/13/2005 12:13:48 PM

Disposition:

G10 face plate cut to expose lead extender splice block; bus lead soldered directly to lead extender splice block.

Responsible Authority: Andy Hocker

Date: 6/13/2005

Corrective Action to Prevent Recurrence:

Minimize handling of corrector leads.
Disposition verify notes: No Traveler Change.

Responsible Authority: Andy Hocker

Date: 6/13/2005

Corrective Action/Disposition Verified By: John Szostak

Date: 7/22/2005 2:17:36 PM

Will Configuration be affected?: ☐ YES ☑ NO

Identified problem area:

☐ Material ☐ Manpower ☑ Method ☐ Machine ☐ Measurement

Reviewed By: Bob Jensen

Date: 8/2/2005

Traveler Title:	Specification No:	Revision:	DR No:
LHC Q1 LMQXA Cold Mass Module Assembly Traveler	333754	F	4260

Step No:	Drawing No:	Routing Form No:	Serial No:	Rework ID:
9.7	390526		LMQXA08	0

Discrepancy Description:

Non IP End dome was off 180 degrees in rotation when it was scribed on module assembly table.

Originator: Damon Bice

Date: 6/15/2005 5:05:03 PM

Cause of Nonconformance:

The end dome was not orientated properly for scribing. This was a technician error.

Responsible Authority: Thomas Page

Date: 6/16/2005 12:54:11 PM

Disposition:

Re-level the magnet using the recorded measurement written on the cold mass. Position and level the dome in the correct orientation. Check the level using a precision bubble level and by transferring the scribes from the original positioning. Once level, re-scribe the dome and cold mass. Before welding, check to ensure the cold mass pipe on the dome is properly ground to prevent damage to the bus.

Responsible Authority: Thomas Page

Date: 6/16/2005

Corrective Action to Prevent Recurrence:

Ensure the dome is orientated properly before scribing. Add steps to Traveler.
Disposition verify notes: (TRR No. 1746)

Responsible Authority: Thomas Page

Date: 6/16/2005

Corrective Action/Disposition Verified By: John Szostak

Date: 7/22/2005 1:45:11 PM

Will Configuration be affected?: ☐ YES ☑ NO

Identified problem area:

☐ Material ☐ Manpower ☑ Method ☐ Machine ☐ Measurement

Reviewed By: Bob Jensen

Date: 8/2/2005

Traveler Title:	Specification No:	Revision:	DR No:
LHC Q1 LMQXA Cold Mass Module Assembly Traveler	333754	F	4265

Step No:	Drawing No:	Routing Form No:	Serial No:	Rework ID:
12.2	390526		LMQXA08	0

Discrepancy Description:

Voltage tap EE8121 (H1A tap) does not appear to be functional.

Originator: Damon Bice

Date: 6/22/2005 8:01:12 AM

Cause of Nonconformance:

Voltage tap lead likely broken.

Responsible Authority: Andy Hocker

Date: 6/22/2005 3:25:55 PM

Disposition:

Solder new voltage tap to just before the lead-to-corrector splice. Check resistance and strain relieve with green putty. Clip off and insulate faulty lead.

Responsible Authority: Andy Hocker

Date: 6/22/2005

Corrective Action to Prevent Recurrence:

Minimize handling of leads.
Disposition verify notes: No Traveler Change.

Responsible Authority: Andy Hocker

Date: 6/22/2005

Corrective Action/Disposition Verified By: John Szostak

Date: 7/22/2005 8:29:57 AM

Will Configuration be affected?: ☐ YES ☑ NO

Identified problem area:

☐ Material ☐ Manpower ☐ Method ☐ Machine ☑ Measurement

Reviewed By: Bob Jensen

Date: 7/22/2005

Traveler Title:	Specification No:	Revision:	DR No:
LHC Q1 LMQXA Cold Mass Module Assembly Traveler	333754	F	4267

Step No:	Drawing No:	Routing Form No:	Serial No:	Rework ID:
13.1	369894		LMQXA08	0

Discrepancy Description:

RTD (TT8321) is open. The technicians from building one found this out during their inspection of the hypertronic's connector.

Originator: Steve Gould

Date: 6/29/2005 10:08:36 AM

Cause of Nonconformance:

Redundant RTD TT8321 is open. Reason unknown. RTD was fine prior to installation of hypertronics connector.

Responsible Authority: Andy Hocker

Date: 7/1/2005 8:05:57 AM

Disposition:

New RTD mounted AT NON-IP END inside the helium pipe that is opposite the pipe carrying the power leads. New RTD leads routed into the end dome and back out with the normal instrumentation wire bundle. Leads to open RTD removed from hypertronics connector and insulated. New RTD wired into hypertronics connector.

Responsible Authority: Andy Hocker

Date: 7/1/2005

Corrective Action to Prevent Recurrence:

The RTD resistances should be measured immediately prior to soldering to the hypertronics connector and immediately afterward, in order to confirm or exonerate the soldering process as the source of the failure.
Disposition verify notes: No Traveler Change. Andy Hocker verbally informed IB1 techs of the need to measure RTD resistances before and after soldering, per the Corrective Action.

Responsible Authority: Andy Hocker

Date: 7/1/2005

Corrective Action/Disposition Verified By: John Szostak

Date: 7/22/2005 8:36:50 AM

Will Configuration be affected?: ☐ YES ☑ NO

Identified problem area:

☐ Material ☐ Manpower ☑ Method ☐ Machine ☐ Measurement

Reviewed By: Bob Jensen

Date: 7/22/2005

CERN
CH-1211 Geneva 23
Switzerland

AT MEL Document No.
LHC-MCBX-FR-0001 rev. **1.0**

EDMS Document No.
---

the **Large Hadron Collider** project

Certificate of Conformity

Part name:	MCBX Inner Triplet Dipole Corrector		
LHC Identification No.:	HCMCBX_001-SI000011	Serial No.:	HCMCBX_001-SI000011
Shipped To:	CERN	***Shipment No:***	***11***
		Shipment	***05/09/03***
Manufacturer:	SIGMAPHI	Contract No.:	F375/LHC/LHC
Related tech. Specification:	LHC-MCBX-CI-0001 and addenda		
Related drawings:	LHCMCBX_0012 (1525-CN-1001)		
Responsible person at CERN:	Mikko Karppinen	***Tel.***	+41 22 767 4305
		E-mail.	Mikko.Karppinen@cern.ch
Responsible person at SIGMAPHI:	Damien Neuvéglise	***Tel.***	+33 2 97 01 08 80
		E-mail.	dneuveglise@sigmaphi.fr

SIGMAPHI certifies that the delivered material conforms to the technical specification mentioned above:

Date: 30/06/04	***Name: D.Neuvéglise***	***Signature: D.Neuvéglise***

Acceptance test results

		MCBXV (Inner)	***MCBXH (Outer)***	***Remarks:***
RT dc resistance (Ω):	***SIGMAPHI:***	***17.5***	***21.4***	
	CERN:	***17.7***	***21.3***	
	CMA[1]:	17.44	21.19	
Inductance @1 kHz/100 Hz (mH)	***SIGMAPHI:***	***66.15 / 112.66***	***58.37/ 98***	
	CERN	***63/84***	***58.5/98***	
	CMA:	63.08 / 84.56	58.53 / 98.08	
R.T. leakage current to ground @ 1.5 kV (μA):	***SIGMAPHI:***	***10E-9A***	***16.7E-9A***	
	CERN:	***10E-9A***	***60e-9A***	
	CMA:			

	Cold Mass Assembler
Visual inspection	
Name / Signature	
Date	

Accepted: ☒

Rejected: ☐

Comments (SigmaPhi):	

Comments (CERN):	***The magnetic axis of this assembly has been measured at warm.***
	The scribe line is made relative to the measured field angle at warm at CERN (correction -0.44 mrad relative to the dowel pin holes on the connection plate(=0.08mm clockwise))
	During the combined powering field was rotated 0-360 deg at 95% of the nominal current @ 4.3 K.
	During the indivual powering the MCBXV and MCBXH reached 700 A and 600 A respectively.

Comments (CMA):	

CERN LHC MQXA

Acceptance Test at FNAL

QUALITY RECORD

Cryogenics Science Center

KEK, High Energy Accelerator Research Organization

Magnet ID :_____

Date of approval :_____

Approved by :_____ (FNAL)

:_____ (KEK)

Ver. 0
Ver A (with initial results)

1. Appearance Check

Procedure	Criteria
Check appearance of the magnet by visual inspection.	No harmful defects or deformation
Result at TOSHIBA	
Acceptable	
Result at FNAL	

2. Interface Dimensions



1) Dimensions	Unit:mm
Procedure	**Criteria**
1) Dimension Check Measure following dimensions a, b, c : Measuring range: every 45 deg. from 0 deg. d : Splice Box : four points	
a) Machine center - Interface	a) 3330 –6/+0
b) Interface outer diameter (Doel,Doer)	b) ϕ468 –4/+0
c) Interface inner diameter (Diel,Dier)	c) ϕ450 –4/+0
d) End Ring - Splice box(Eg)	d) 7 -5/+5

Result at TOSHIBA

Critera	3330 -6/+0		ϕ468 -4/+0		ϕ450 -4/+0		7
Position	Fl	Fr	Doel	Doer	Diel	Dier	Eg
0 deg.	3329.0	3330.0	466.95	466.90	448.73	448.46	6.20
45 deg.	3329.0	3330.0	466.85	466.54	448.57	448.50	
90 deg.	3329.0	3329.5	467.27	467.72	448.79	449.21	6.50
135 deg.	3329.0	3329.0	466.91	466.54	448.97	448.52	
180 deg.	3329.0	3329.0					5.98
225 deg.	3329.5	3330.0					
270 deg.	3329.5	3329.5					6.37
315 deg.	3329.5	3330.0					
Result	Acceptable		Acceptable		Acceptable		Acceptable

Result at FNAL

Critera	3330 -6/+0		ϕ468 -4/+0		ϕ450 -4/+0		7
Position	Fl	Fr	Doel	Doer	Diel	Dier	Eg
0 deg.	3328.5	3329.0					
45 deg.							
90 deg.	3329.0	3329.0					
135 deg.							
180 deg.							
225 deg.							
270 deg.	3329.0	3329.0					
315 deg.							
Result							

2) End ring interface		
Procedure		Criteria
Check the weld edge preparation using ϕ449 +0/-0.02 gauge.		1) The gauge shall be inserted into the end ring. 2) Measurement data will be reported if the gage cannot be inserted.
Measurement part	Result at TOSHIBA	Remarks
LE side	Acceptable	------
RE side	Acceptable	------
Measurement part	Result at FNAL	Remarks
LE side		
RE side		

3) Radial envelope	
Procedure	Criteria
Check shell radial envelope using ϕ530mm gauge. (dummy cold-mass support)	The gauge shall pass the magnet.
Result at TOSHIBA	
Acceptable	
Result at FNAL	

4) Magnet bore	
Procedure	Criteria
Check appearance of the magnet bore by visual inspection.	No harmful defects or deformation
Result at TOSHIBA	
Acceptable M.P.Lap was damaged at end section (LE side and RE side)	
Result at FNAL	

5) Magnet bus slot	
Procedure	Criteria
Check the bus slot using bus line model gauge.	The gauge shall pass the magnet bus slot.
Result at TOSHIBA	
Acceptable	
Result at FNAL	

6) Weight	
Procedure	Criteria
Measure the magnet weight.	Weight < 8500kg
Result at TOSHIBA	
8320 Kg	Acceptable
Result at FNAL	

7) Length of magnet lead, QPH wire, Voltage taps		
Procedure	Criteria	
Check the lengths of magnet lead, QPH wire, voltage taps.	1) Magnet lead : > 500mm from magnet LE end plate 2) Voltage taps wire : > 2000mm from magnet LE end plate 3) QPH wire : >2000mm from magnet LE end plate	
Result at TOSHIBA		
Measuring wire	Measured Value	Result
1) Magnet lead	500mm	Acceptable
2) Voltage taps	>2000mm	Acceptable
3) QPH wire	2000mm	Acceptable
Result at FNAL		
Measuring wire	Measured Value	Result
1) Magnet lead		
2) Voltage taps		
3) QPH wire		



8) Cable tags	
Procedure	Criteria
Check the cable tags.	Consistent to the tag No. table.

[illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]
	[illegible]	[illegible]
	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]
	[illegible]	[illegible]

Result at TOSHIBA	
1)Voltage taps	Acceptable
2)Quench heaters	Acceptable
Result at FNAL	
1)Voltage taps	
2)Quench heaters	

3. Coil Resistance

Procedure	Criteria
Measure the magnet total resistance and coil temperature at coil current of DC1A. Calculate resistance at 20 °C; R_{20}. $R_{20}=V/I/(1+0.00393*(T_{coil}-20))$ V : Voltage between magnet leads (V) I : Coil current obtained by shut resistor (A) T_{coil} : coil temperature (°C)	1) Compare with R_{20} at TOSHIBA. Variation of R_{20} < 0.005 Ω 2) Voltage taps(C-A, C-B): Measurement Only

Result at TOSHIBA

T_{coil}	Not Reported

Magnet total voltage (V)	Current (A)	Magnet total resistance R_{20} (Ω)
Not Reported	Not Reported	6.81346

Voltage taps tag No.	V (V)	I (A)	R_{20} (Ω)	Voltage taps tag No.	V (V)	I (A)	R_{20} (Ω)
C1 - A1	Not Reported	Not Reported	3.40516	C2 - A1	Not Reported	Not Reported	3.40448
C1 - A2	Not Reported	Not Reported	3.40516	C2 - A2	Not Reported	Not Reported	3.40448
C1 - B1	Not Reported	Not Reported	3.40368	C2 - B1	Not Reported	Not Reported	3.40368
C1 - B2	Not Reported	Not Reported	3.40368	C2 - B2	Not Reported	Not Reported	3.40368

Acceptable

Result at FNAL

T_{coil}			
Magnet total voltage (V)	Current (A)	Magnet total resistance R_{20} (Ω)	Variation (Ω) ($R_{20\text{-TOSHIBA}}$ - $R_{20\text{-FNAL}}$)
		6.760	

Voltage taps tag No.	R_{20} (Ω)	Voltage taps tag No.	R_{20} (Ω)
C1 - A1	3.38	C2 - A1	3.38
C1 - A2	3.38	C2 - A2	3.38
C1 - B1	3.38	C2 - B1	3.38
C1 - B2	3.38	C2 - B2	3.38

4. Instrumentations

1) Voltage taps

Procedure	Criteria
Check resistance of all voltage taps by four terminal method at 1A. Magnet lead : Q4 4th : + Magnet lead : Q3 3rd : -	Magnet lead + : A1, A2 (Pole4 Out) Magnet lead - : B1, B2 (Pole3 Out) Center taps : C1, C2 (Pole1 Out) Variation of R_{20}(A1),R_{20}(A2) : < 0.1% Variation of R_{20}(B1),R_{20}(B2) : < 0.1% Variation of R_{20}(C1),R_{20}(C2) : < 0.1%

Result at TOSHIBA

Voltage taps No.	Resistance(Ω)	Voltage taps No.	Resistance(Ω)	Variation(%)	Result
A1	0.00260	A2	0.00260	0.00	Acceptable
C1	3.40718	C2	3.40718	0.00	Acceptable
B1	6.81096	B2	6.81096	0.00	Acceptable

Result at FNAL

Voltage taps No.	Resistance(Ω)	Voltage taps No.	Resistance(Ω)	Variation(%)	Result
A1	.0028	A2	.0028		
C1	3.38	C2	3.38		
B1	6.75	B2	6.75		

2) QPH

Procedure	Criteria
Measure the resistance of QPH.	QPH resistance : 30 +4/-4Ω (HA,HB)

Result at TOSHIBA

QPH No.	QPH Resistance(Ω)	Result
HA	28.8	Acceptable
HB	28.9	Acceptable

Result at FNAL

QPH No.	QPH Resistance(Ω)	Result
HA	28.34	
HB	28.34	

5. Coil Inductance

Procedure	Criteria
Measure inductance of magnet at frequencies of 100Hz and 1kHz using LCR meter.	1) Variation of inductance Voltage taps No. C-A, inductance Voltage taps No. C-B : < 5% 2) Total inductance of the magnet :Measurement only

Result at TOSHIBA

Voltage taps tag No.	100Hz	Result (%)	1kHz	Result (%)	Voltage taps tag No.	100Hz	Result (%)	1kHz	Result (%)
C1 - A1	37.08	0.03	13.314	0.03	C2 - A1	37.08	0.01	13.315	0.04
C1 - A2	37.08		13.314		C2 - A2	37.07		13.315	
C1 - B1	37.07		13.310		C2 - B1	37.07		13.310	
C1 - B2	37.07		13.309		C2 - B2	37.07		13.310	

	100Hz	1kHz
Magnet	87.14	30.94

Acceptable

Result at FNAL

Voltage taps tag No.	100Hz	Result (%)	1kHz	Result (%)	Voltage taps tag No.	100Hz	Result (%)	1kHz	Result (%)
C1 - A1	37.09		13.37		C2 - A1	37.09		13.37	
C1 - A2	37.09		13.37		C2 - A2	37.09		13.37	
C1 - B1	37.08		13.36		C2 - B1	37.08		13.36	
C1 - B2	37.08		13.36		C2 - B2	37.08		13.36	

	100Hz	1kHz
Magnet	87.23	31.33

6. Turn to Turn Insulation

Procedure	Criteria
Apply impulse voltage of 1000V between the magnet leads and record the signal. Instrumentation: Impulse generator, recorder	Compare the signal with one at KEK. Attach rthe chart.
Result at TOSHIBA	
Acceptable	See appendix
Result at FNAL	

7. Coil Insulation

1) Insulation Resistance			
Procedure		Criteria	
Apply 1kV-DC to the coil in 1 min. and measure insulation resistance by using insulation tester. High voltage : Coils Ground : Collar, Yoke, Shell, QPH		Insulation resistance > 100MΩ	
Result at TOSHIBA			
Temperature(°C)	Humidity(%)	Insulation(MΩ)	Result
23	42	> 2000	Acceptable
Result at FNAL			
Temperature(°C)	Humidity(%)	Insulation(MΩ)	Result

2) Hi-pot test			
Procedure		Criteria	
Apply 3kV-DC to the coil in 1 min. and measure leak current or insulation resistance. High voltage : Coil Ground : Collar, Yoke, Shell, QPH		No break down Record leak current or resistance.	
Result at TOSHIBA			
Temperature (°C)	Humidity (%)	Leak current (mA)	Result
23	42	0.00	Acceptable
Result at FNAL			
Temperature (°C)	Humidity (%)	Leak current or resistance	Result

8. QPH Insulation

1) Insulation Resistance

Procedure	Criteria
Apply 1kV-DC to the QPH in 1 min. and measure insulation resistance by using insulation tester. High voltage : QPH Ground : Coil, Collar, Yoke, Shell	Insulation resistance > 100MΩ

Result at TOSHIBA

Heater No.	Temperature (°C)	Humidity (%)	Insulation(MΩ)	Result
HA	23	42	> 2000	Acceptable
HB			> 2000	Acceptable

Result at FNAL

Heater No.	Temperature (°C)	Humidity (%)	Insulation(MΩ)	Result
HA				
HB				

2) Hi-pot test

Procedure	Criteria
Apply 3kV-DC to the QPH in 1 min. and measure leak current or insulation resistance. High voltage : QPH Ground : Coil, Collar, Yoke, Shell	No break down Record leak current or resistance.

Result at TOSHIBA

Heater No.	Temperature (°C)	Humidity (%)	Leak current (mA)	Result
HA	23	42	0.00	Acceptable
HB			0.00	Acceptable

Result at FNAL

Heater No.	Temperature (°C)	Humidity (%)	Leak current or resistance	Result
HA				
HB				

9. QPH Discharge Test

1) Appearance check	
Procedure	Criteria
Check appearance of QPH wires by visual inspection.	No harmful defects or deformation.
Result at TOSHIBA	
Acceptable	
Result at FNAL	

2) QPH discharge test		
Procedure		Criteria
Charge the power supply above 850 V and fire QPHs.		No strange signal observed. Attach the chart.
Result at TOSHIBA		
HA	Acceptable	See appendix
HB	Acceptable	See appendix

3) QPH resistance				
Procedure		Criteria		
Measure resistance before/after the discharge test.		Resistance change < 10%		
Result at TOSHIBA				
QPH No.	Before (Ω)	After (Ω)	Variation (%)	Result
HA	28.8	28.8	0.0	Acceptable
HB	28.9	28.9	0.0	Acceptable
Result at FNAL				
QPH No.	Before (Ω)	After (Ω)	Variation (%)	Result
HA				
HB				

FORM #1 FIXED VOLTAGE TAPS _1A_FORM

Test of Q1 FVTs

Apply 1 A current between BUS #1 & BUS #2
Connect Current Source: BUS #1 to Negative and BUS #2 to Positive
Use a 3457 or equilvent DVM and record measurement to 4 decimal places
Use 2 wires Voltage Measurements Technique:
1. Connect DVM LO wire to BUS#1 (or Negative output of Power source)
2. HI wire of DVM will move through breakout box to measure V
DO NOT USE DC CURRENT LARGER THAN 2A.
DO NOT RUN DC CURRENT THROUGH MAGNET LONGER THAN 30MIN.

BUS #1
BUS #2

POWER BUS LOCATION

HYPERTRONICS CONNECTOR		FNAL Labels	Description	Break Box Labels	Expected Voltage, V	Measured, V
Module	Pin					
M2	1	VTa1Q1	Q1 Lead Voltage Tap "a", primary	EE1111	7.0000	6.9105
M2	2	VTa2Q1	Q1 Lead Voltage Tap "a", redundant	EE1121	7.0000	6.9104
M2	5	VTb1Q1	Q1 lead Voltage Tap "b", primary	EE1311	0.0030	0.002305
M3	5	VTb2Q1	Q1 Lead Voltage Tap "b" redundant	EE1321	0.0030	0.002304
M2	3	VTc1Q1	Q1 Center Voltage Tap "c", primary	EE1211	3.5000	3.4564
M2	4	VTc2Q1	Q1 Center Voltage Tap "c", redundant	EE1221	3.5000	3.4562

Across BUS #1 and BUS #2	6.9125 V

LMQXA08

1/5

Form #2 CRYO HEATER CHECK_OUT

MEASURE RESISTANCE ACROSS EACH HEATER USING HANDHELD METER
MEASURE RESISTANCE FROM HEATER TO GND USING HANDHELD METER

Module	Pin		*Expected Resistance, OHM*	*Measured Resistance, OHM*	FNAL Label	Description
M7	*1*	**EH8311+**	**17**	**17.65**	W1aQ1	*Q1 Cryogenic Heater lead end - wire toward cold mass end plate (CERN #1 I+)*
M7	*2*	**EH8311-**			W2aQ1	*Q1 Cryogenic Heater lead end - wire toward cold mass mag center (CERN #1 I-)*
M7	*3*	**EH8321+**	**17**	**17.89**	W1bQ1	*Q1 Cryogenic Heater non-lead end-wire toward cold mass end plate (CERN #2 I+)*
M7	*4*	**EH8321-**			W2bQ1	*Q1 Cryogenic Heater non-lead end-wire toward cold mass mag center (CERN #2 I-)*

M7	*1*	**EH8311+**	**more than 20MOHM**	**Inf**	W1aQ1	*Q1 Cryogenic Heater lead end - wire toward cold mass end plate (CERN #1 I+)*
		GND				
M7	*3*	**EH8321+**	**more than 20MOHM**	**Inf**	W1bQ1	*Q1 Cryogenic Heater non-lead end-wire toward cold mass end plate (CERN #2 I+)*
		GND				

LMQXA08 2/5

Form #3 PROTECTION STRIP HEATERS

MEASURE RESISTANCE ACROSS EACH HEATER USING HANDHELD METER
MEASURE RESISTANCE FROM HEATER TO GND USING HANDHELD METER
MEASURE RESISTANCE FROM HEATER TO COIL USING HANDHELD METER

M9	1	YT1111-	30	30.18	H2aQ1	Q1 Protection (Strip) Heater, 1-4 & 2-3 circuit (FNAL lead A-) (CERN lead #1-)
M9	3	YT1111+			H1aQ1	Q1 Protection (Strip) Heater, 1-4 & 2-3 circuit (FNAL lead A+) (CERN lead #1+)
M9	2	YT1121+	30	30.25	H1bQ1	Q1 Protection (Strip) Heater, 1-2 & 3-4 circuit (FNAL lead B+) (CERN lead#2+)
M9	4	YT1121-			H2bQ1	Q1 Protection (Strip) Heater, 1-2 & 3-4 circuit (FNAL lead B-) (CERN lead #2-)

M9	1	YT1111- GND	more than 20MOHM	INF	H2aQ1	Q1 Protection (Strip) Heater, 1-4 & 2-3 circuit (FNAL lead A-) (CERN lead #1-)
M9	2	YT1121+ GND	more than 20MOHM	INF	H1bQ1	Q1 Protection (Strip) Heater, 1-2 & 3-4 circuit (FNAL lead B+) (CERN lead#2+)

M9	1	YT1111- COIL	more than 20MOHM	INF	H2aQ1	Q1 Protection (Strip) Heater, 1-4 & 2-3 circuit (FNAL lead A-) (CERN lead #1-)
M9	2	YT1121+ COIL	more than 20MOHM	INF	H1bQ1	Q1 Protection (Strip) Heater, 1-2 & 3-4 circuit (FNAL lead B+) (CERN lead#2+)

LMQXA08 3/5

Form#4 RTDs Measurements

MEASURE RESISTANCE ACROSS EACH RTD USING A FOUR WIRE METER
MEASURE RESISTANCE FROM RTD TO GROUND USING HANDHELD METER
MEASURE RESISTANCE FROM RTD TO THE COIL USING HANDHELD METER

Module	Pin	Breakout BOX Labels	Expected Resistance, OHM	Measured Resistance OHM	FNAL Label	Description
M12	1	TT8311 I+	57	66.26	TaQ1_I+	Q1 RTD, primary Wire color: Yellow
M12	2	TT8311 I-			TaQ1_I-	Q1 RTD, primary Wire color: Green
M12	3	TT8311 U+			TaQ1_V+	Q1 RTD, primary Wire color: Black
M12	4	TT8311 U-			TaQ1_V-	Q1 RTD, primary Wire color: Red
M12	5	TT8321 I+	57	67.05	TbQ1_I+	Q1 RTD, redundant: Wire color: Yellow
M12	6	TT8321 I-			TbQ1_I-	Q1 RTD, redundant: Wire color: Green
M12	11	TT8321 U+			TbQ1_V+	Q1 RTD, redundant: Wire color: Black
M12	10	TT8321 U-			TbQ1_V-	Q1 RTD, redundant: Wire color: Red
M12	1	TT8311 I+ GND	more than 20MOHM	INF	TaQ1_I+	Q1 RTD, primary Wire color: Yellow
M12	5	TT8321 I+ GND	more than 20MOHM	INF	TbQ1_I+	Q1 RTD, redundant: Wire color: Yellow
M12	1	TT8311 I+ COIL	more than 20MOHM	INF	TaQ1_I+	Q1 RTD, primary Wire color: Yellow
M12	5	TT8321 I+ COIL	more than 20MOHM	INF	TbQ1_I+	Q1 RTD, redundant: Wire color: Yellow

LMQXA08 4/5

Ccoil bus #	NA	3	4	1	2
	XXX	V1A	V1B	H1A	H1B

POSITION OF CCOIL BUS

Form#5 Correction COILs

MEASURE RESISTANCE ACROSS BOTH CCOIL BUSES
MEASURE RESISTANCE FROM CCOIL TO GROUND
MEASURE RESISTANCE BETWEEN BOTH TAPS
MEASURE RESISTANCE FROM EACH TAP TO CCOIL BUS

			Expected	Measured(ohms)
Horizontal Corrector Coil resistance				
H1-A	CCOIL BUS #1		19 OHMS	21.68
H1-B	CCOIL BUS #2			
	Vertical Corrector Coil resistance			
V1-A	CCOIL BUS #3		22 OHMS	17.78
V1-B	CCOIL BUS #4			
H1-A	CCOIL BUS #1		more than 20MOHM	INFINITE
	GND			
V1-A	CCOIL BUS #3		more than 20MOHM	INFINITE
	GND			
M5	1	EE8121	more than 20MOHM	INFINITE
M5	2	EE8111		
M5	1	EE8121	less than 5 OHMS	0.93
		Ccoil Bus#1		
M5	2	EE8111	less than 5 OHMS	1.05
		Ccoil Bus#3		
M5	1	EE8121	more than 14 OHMS	22.45
		Ccoil Bus#2		
M5	2	EE8111	more than 14 OHMS	18.57
		Ccoil Bus#4		

VTH1	*Corrector voltage tap Q1-H1 (skew dipole) (on MCBX, MCBXH, A+ lead)*
VTV1	*Corrector voltage tap Q1-V1 (normal dipole) (on MCBX, MCBXV, A+ lead)*
VTH1	*Corrector voltage tap Q1-H1 (skew dipole) (on MCBX, MCBXH, A+ lead)*
VTV1	*Corrector voltage tap Q1-V1 (normal dipole) (on MCBX, MCBXV, A+ lead)*
VTH1	*Corrector voltage tap Q1-H1 (skew dipole) (on MCBX, MCBXH, A+ lead)*
VTV1	*Corrector voltage tap Q1-V1 (normal dipole) (on MCBX, MCBXV, A+ lead)*

LMQXA08 5/5

ADDITIONAL PARTS REQUEST

ADDITIONAL PARTS REQUEST FORM SHALL BE USED TO ACCESS ALL ITEMS FROM INVENTORY WITH THE EXCEPTION OF PARTS KITS.

THIS FORM MUST BE SIGNED BY AN ACQUISITIONER BEFORE BRINGING TO THE STOCKROOM

MAGNET OR COIL # *LMQXA-08*

REQUESTED BY *Damon Bice*

DATE REQUESTED *6-2-05*

DELIVER TO *P/U*

BUDGET CODE *300/1.1.13.4*

NEED BY DATE *6-2-05*

JOB TICKET # _____

MMR # _____

MACHINE SHOP REQ. # _____

PO # _____

PURCHASE RELEASE # _____

OTHER _____

PARTS STATUS (CHECK ONE)

- ☐ DEFECTIVE PARTS ISSUED
- ☐ PARTS SCRAPPED
- ☐ A/R ITEMS
- ☐ DEFECTIVE ASSEMBLY
- ☒ MISSING FROM KIT ALREADY ISSUED
- ☐ INDIVIDUAL PARTS
- ☐ CONSUMABLES
- ☐ PARTS LOST

ACQUISITIONER SIGNATURE [signature] **ID#** 4223 **DATE** 6/2/05

PLEASE INDICATE REVISION REQUIRED

LOCATION	PART #	REV	QTY	DESCRIPTION	RF #	SIR #
IB#4 BIN	*MB 390228*		*4*	*Corrector mounting washer*	83114	

Stock 74

STOCKROOM SIGNATURE [signature] **ID#** 11939 **DATE** 6/2/05

PARTS DELETED FROM DATABASE [signature] **ID#** _____ **DATE** _____

A COPY OF THIS FORM IS TO BE INCLUDED IN WITH THE TRAVELER

PARTS RECEIVED BY [signature] **ID#** 13441 **DATE** 6/2/05

To measure the resistance of a Thermometer (RTD):

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
   U+ (Black) to Sense HI
   I+ (Yellow) to Input HI
   U- (Red) to Sense LO
   I- (Green) to Input LO
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
8. Read resistance in ohms and record in traveler.



To measure the resistance of a Cryogenic (Warm-up) Heater

1. Use Hewlett Packard HP3457A digital multimeter.
2. Record temperature of building within +/- 5 degrees.
3. Press line button to turn line on.
4. Connect wires as shown in Figure below.
5. Push blue button (function key) once.
6. Push OHMF button.
7. Verify arrow in readout is above the 4WΩ (meaning a 4 wire resistance measurement).
   Note: Although this is technically a 4 wire measurement, it is effectively a 2 wire measurement, since there are only 2 wires connected to each heater.
8. Read resistance in ohms and record in traveler.



Q1 - RTD's and Cryogenic (warm-up) Heaters					
Temperature of Building (± 5°): 70°					
Component	Fermi	CERN	Range	MFR. Ω	Resistance
Q1 RTD, primary	TaQ1	TT8311	60 to 70 Ω	72.226	66.33 Ω
Q1 RTD, redundant	TbQ1	TT8321	60 to 70 Ω	65.029	67.092 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at top (CERN #1 I+)	W1aQ1	EH8311+	16 to 18.5 Ω		17.55 Ω
Q1 Cryogenic (warm-up) Heater (LE) - wire at bottom (CERN #1 I-)	W2aQ1	EH8311-			
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at top (CERN #2 I+)	W1bQ1	EH8321+	16 to 18.5 Ω		17.77 Ω
Q1 Cryogenic (warm-up) Heater (Non-LE) - wire at bottom (CERN #2 I-)	W2bQ1	EH8321-			

Technician(s) _____ Date 7/6/05

Using the Hewlett Packard HP3457A digital multimeter, measure the Protection (Strip) Heater Resistance for Q1.

Q1 Protection (Strip) Heater Resistance					
Fermi	CERN	KEK	Description	Limit	Resistance
H1aQ1	YT1111+	HA1	Circuit A	28 to 32 Ω	30.09 Ω
H2aQ1	YT1111-	HA2			
H1bQ1	YT1121+	HB1	Circuit B	28 to 32 Ω	30.115 Ω
H2bQ1	YT1121-	HB2			

Technician(s) _____ Date 7/6/05

Cryogenic Thermometer Traveller

DESCRIPTION

Part description:	Cryogenic thermometer	**Top Assembly Identification:**	LMQXA08
Part Identification:	HCQITESCXT-CR013780		
Serial Number:	CX_LS_X17277	**Manufactured By:**	Fermilab

CABLING

Replaces CX_LS_X17251

Connector Tag Name TT8321



Fixing Case

Thread ☐
Hole ☐
Stud ☐

Thermometer Cable for Type ST

ρ (300 K) = 0.32 Ohm/m
Copper AWG 30
Length = ☐ m

Extension

ρ (300 K) = 0.07 Ohm/m
Copper AWG 24
Length: 0.8 m

CHECKS

Intervention	Date/ DD-MMM-YYYY	Check Point	R(U+,U-,I+,I-) [Ohm] 4W	R(U-,I-) [Ohm] 2W	R(U+,I+) [Ohm] 2W	R(U+,GND) [Ohm] 2W	Temperature [K]	Firm/Laboratory	Checked by
Calibration	*04-Feb-2002*	T	*66.73*	*n.a*	*n.a*	*OVL*	*Ambient*	*IPN*	*Joly*
Expedition	*12-Mar-2003*	T	*65.029*	*0.1*	*0.1*	*OVL*	*293*	*CERN*	*Grivat*
Reception		T W C	67,98					Fermi	Schewe
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							

Cryogenic Thermometer Traveller

DESCRIPTION

Part description:	Cryogenic thermometer	**Top Assembly Identification:**	LMQXA08
Part Identification:	HCQITESCXT-CR013400	**Manufactured By:**	Fermilab
Serial Number:	CX_LS_X17210		

CABLING



Fixing Case

Thread ☐
Hole ☐
Stud ☐

Thermometer Cable for Type ST

ρ (300 K) = 0.32 Ohm/m
Copper AWG 30
Length = ☐ m

Extension

ρ (300 K) = 0.07 Ohm/m
Copper AWG 24
Length: 0.8 m

CHECKS

Intervention	Date/ DD-MMM-YYYY	Check Point	R(U+,U-,I+,I-) [Ohm] 4W	R(U-,I-) [Ohm] 2W	R(U+,I+) [Ohm] 2W	R(U+,GND) [Ohm] 2W	Temperature [K]	Firm/Laboratory	Checked by
Calibration	*04-Feb-2002*	T	*73.99*	*n.a*	*n.a*	*OVL*	*Ambient*	*IPN*	*Joly*
Expedition	*12-Mar-2003*	T	*72.226*	*0.1*	*0.1*	*OVL*	*293*	*CERN*	*Grivat*
Reception		T W C	73.76					Fermi	Schewe
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							

In Case of problem, do not hesitate to contact Responsible person at CERN. Tel:+41 22 767 4266

Cryogenic Thermometer Traveller

DESCRIPTION

Part description:	Cryogenic thermometer	**Top Assembly Identification:**	LMQXA08
Part Identification:	HCQITESCXT-CR013660		
Serial Number:	CX_LS_X17251	**Manufactured By:**	Fermilab

(Removed and replaced by CX_LS_X17277 [illegible])

CABLING



Fixing Case

Thread ☐
Hole ☐
Stud ☐

Thermometer Cable for Type ST

ρ (300 K) = 0.32 Ohm/m
Copper AWG 30
Length = ☐ m

Extension

ρ (300 K) = 0.07 Ohm/m
Copper AWG 24
Length: 0.8 m

CHECKS

Intervention	Date/ DD-MMM-YYYY	Check Point	R(U+,U-,I+,I-) [Ohm] 4W	R(U-,I-) [Ohm] 2W	R(U+,I+) [Ohm] 2W	R(U+,GND) [Ohm] 2W	Temperature [K]	Firm/Laboratory	Checked by
Calibration	*04-Feb-2002*	T	*67.62*	*n.a*	*n.a*	*OVL*	*Ambient*	*IPN*	*Joly*
Expedition	*12-Mar-2003*	T	*66.462*	*0.1*	*0.1*	*OVL*	*293*	*CERN*	*Grivat*
Reception		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							
		T W C							