LHe Tank Dye Penetrant Reports

Meyer Tool & Mfg., Inc.

4601 W. Southwest Hwy., Oak Lawn, Illinois 60453
708 / 425-9080
Fax 708 / 425-2612

DYE PENETRANT INSPECTION REPORT

Job No.: 00918 FEED BOX "A" Inspected By: EUGENE THEDENS (COVER PASSES) MIKE JEENINGA (ROOT PASSES)

Customer No.: _____ Customer Name: L.B.N.2 Date: 4-22-05

Dwg No.: 24C351 Item No.: -35 (25I119) -36 (25M802)

Procedure Used: [X] MTM-MP-1050-2 [ ] Other_____

Acceptance Used: [X] MTM-MP-1050-2 [ ] Other_____

	Penetrant	Developer	Remover	Cleaner
SHERWIN DUBL-CHEK Type:	DP-51	D-100	DR-60	DR-60
Batch:	87647	F330	0844	0844

Dwell Time: 10 MIN Developer Time: 7 MIN

Additional Comments: _____

	Description (1)	Results (2)	(3)
25I119	ROOT PASS	NO DEFECTS FOUND	
25M802	ROOT PASS	NO DEFECTS FOUND	
25I119	Cover Pass	No Defect's found	
25M802	Cover Pass	No Defect's found	

Non Conformance Disposition: _____

Dispositioned By: _____ Date: _____

Notes: (1) Provide Sketch if needed.
(2) Asterick (*) all non conformances.
(3) Consecutively number all non conformances.

Meyer Tool & Mfg., Inc.

4601 W. Southwest Hwy., Oak Lawn, Illinois 60453
708 / 425-9080
Fax 708 / 425-2612

DYE PENETRANT INSPECTION REPORT

Job No.: 00918 - 0099 Inspected By: MIKE JEENINGA / CINDY DYRDA

Customer No.: _____ Customer Name: L.B.N.L Date: 5/5/05

Dwg No.: 24C351 (Box "A") Item No.: 25I119 / 25M802

Procedure Used: [X] MTM-MP-1050-2 [ ] Other_____ Acceptance Used: [X] MTM-MP-1050-2 [ ] Other_____

SHERWIN DUBL-CHEK

	Penetrant	Developer	Remover	Cleaner
Type:	DP - 51	D -100	DR-60	DR -60
Batch:	87G47	F 330	0844	0844

Dwell Time: 10 MIN. Developer Time: 7 MIN.

Additional Comments: _____

Description (1)	Results (2)	(3)
ROOT PASS	NO DEFECTS	
COVER PASS	NO DEFECTS	

Non Conformance Disposition: _____

Dispositioned By: _____ Date: _____

Notes: (1) Provide Sketch if needed.
(2) Asterick (*) all non conformances.
(3) Consecutively number all non conformances.