MQX2 Hipot in Helium

00918-0014

FEED BOX "F" LQX IN HELIUM

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 02:45:02 AM

User Name: Glen Konecky

Device Tested

Model Number: feed box F LQX

Serial Number: A1 thruA5 t0 M2

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:01:46 AM

User Name: Glen Koreky

Device Tested

Model Number: feed box F LQX

Serial Number: A6 thru B4 to M3

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:09:39 AM

User Name: Glen Koreky

Device Tested

Model Number: feed box F LQX

Serial Number: B5 thhru C3 to M4

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:25:47 AM

User Name: [illegible]

Device Tested

Model Number: feed box F LQX

Serial Number: C4 thru D2 to M5

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:44:23 AM

User Name: Glen Koenig

Device Tested

Model Number: feed box F LQX

Serial Number: D-3 THRU D6 TO M6

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:29:18 AM

User Name: Glen Koretz

Device Tested

Model Number: feed box F LQX

Serial Number: E1 thru E4 to M8

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:33:55 AM

User Name: Glen Horsky

Device Tested

Model Number: feed box F LQX

Serial Number: E5 thru F2 to M9

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:39:08 AM

User Name: Glen Kreby

Device Tested

Model Number: feed box F LQX

Serial Number: F3 thru F6 to M10

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:44:23 AM

User Name: Allen Moreby

Device Tested

Model Number: feed box F LQX

Serial Number: G1 thruG3 toM17

Setup Filename: Leads In Air & He

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:00:30 AM

User Name: Glen Korab

Device Tested

Model Number: feed box F LQX

Serial Number: G4 thruG5 toM18

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 03:56:27 AM

User Name: Glen Nowby

Device Tested

Model Number: feed box F LQX

Serial Number: G6 thru H2 toM19

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:05:32 AM

User Name: Glen Kirsch

Device Tested

Model Number: feed box F LQX

Serial Number: H3 thruH4 to M20

Setup Filename: Leads In Air & He

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:09:17 AM

User Name: Glen Hardy

Device Tested

Model Number: feed box F LQX

Serial Number: H5 thru I1 toM21

Setup Filename: Leads In Air & He

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:17:17 AM

User Name: Glenn Horsley

Device Tested

Model Number: feed box F LQX

Serial Number: I2thruI3 to M22

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:20:34 AM

User Name: Glen Mowery

Device Tested

Model Number: feed box F LQX

Serial Number: I4 to M23

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	26	1	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:26:20 AM

User Name: Glen Nowky

Device Tested

Model Number: feed box F LQX

Serial Number: J5thru J2 M12

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	27	1	Pass	Pass	60.0s	0.65KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:30:12 AM

User Name: Glen Moraty

Device Tested

Model Number: feed box F LQX

Serial Number: J3 thruJ6 toM13

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	27	1	Pass	Pass	60.0s	0.65KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:34:18 AM

User Name: Glen Koreby

Device Tested

Model Number: feed box F LQX

Serial Number: K1 thru K4 to M14

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	27	1	Pass	Pass	60.0s	0.65KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 05/10/2005

Test Time: 04:39:07 AM

User Name: Glen Kraly

Device Tested

Model Number: feed box F LQX

Serial Number: K5 thru L2 toM15

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	27	1	Pass	Pass	60.0s	0.65KV	0.0microamps