Hipot Test in Helium Gas

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 01:29:29 AM

User Name: Glen Koenig

Device Tested

Model Number: box F

Serial Number: HTS leads in HE.

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	20	1	Pass	Pass	60.0s	1.40KV	0.0microamps
2	DC Withstand	20	2	Pass	Pass	60.0s	1.40KV	0.0microamps
3	DC Withstand	20	3	Pass	Pass	60.0s	1.40KV	0.0microamps
4	DC Withstand	20	4	Pass	Pass	60.0s	1.40KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 01:50:22 AM

User Name: Glen Koretky

Device Tested

Model Number: box F

Serial Number: 600 AMP / THRU 6 LO. IN HR.

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	21	1	Pass	Pass	60.0s	0.65KV	0.0microamps
2	DC Withstand	21	2	Pass	Pass	60.0s	0.65KV	0.0microamps
3	DC Withstand	21	3	Pass	Pass	60.0s	0.65KV	0.0microamps
4	DC Withstand	21	4	Pass	Pass	60.0s	0.65KV	0.0microamps
5	DC Withstand	21	5	Pass	Pass	60.0s	0.65KV	0.0microamps
6	DC Withstand	21	6	Pass	Pass	60.0s	0.65KV	0.0microamps
~~7~~	~~AC Withstand~~	~~21~~	~~7~~	~~Pass~~	~~Pass~~	~~1.0s~~	~~1.20KV~~	~~0.000mA~~

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 02:11:54 AM

User Name: Glen Gorenty

Device Tested

Model Number: box F

Serial Number: 600amp 7thru 12 in HE.

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	22	1	Pass	Pass	60.0s	0.65KV	0.0microamps
2	DC Withstand	22	2	Pass	Pass	60.0s	0.65KV	0.0microamps
3	DC Withstand	22	3	Pass	Pass	60.0s	0.65KV	0.0microamps
4	DC Withstand	22	4	Pass	Pass	60.0s	0.65KV	0.0microamps
5	DC Withstand	22	5	Pass	Pass	60.0s	0.65KV	0.0microamps
6	DC Withstand	22	6	Pass	Pass	60.0s	0.65KV	0.0microamps
~~7~~	~~AC Withstand~~	~~22~~	~~7~~	~~Pass~~	~~Pass~~	~~1.0s~~	~~1.20KV~~	~~0.000mA~~

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 02:23:01 AM

User Name: Glen Koenig

Device Tested

Model Number: box F

Serial Number: 600amp 13 thru 14 ld in He .

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	23	1	Pass	Pass	60.0s	0.65KV	0.0microamps
2	DC Withstand	23	2	Pass	Pass	60.0s	0.65KV	0.0microamps
~~3~~	~~AC Withstand~~	~~23~~	~~3~~	~~Pass~~	~~Pass~~	~~1.0s~~	~~1.20KV~~	~~0.000mA~~

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 02:48:59 AM

User Name: Glenn Grady

Device Tested

Model Number: box F

Serial Number: 120 amp 1thru8 ld. in HE.

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	24	1	Pass	Pass	60.0s	0.65KV	0.0microamps
2	DC Withstand	24	2	Pass	Pass	60.0s	0.65KV	0.0microamps
3	DC Withstand	24	3	Pass	Pass	60.0s	0.65KV	0.0microamps
4	DC Withstand	24	4	Pass	Pass	60.0s	0.65KV	0.0microamps
5	DC Withstand	24	5	Pass	Pass	60.0s	0.65KV	0.0microamps
6	DC Withstand	24	6	Pass	Pass	60.0s	0.65KV	0.0microamps
7	DC Withstand	24	7	Pass	Pass	60.0s	0.65KV	0.0microamps
8	DC Withstand	24	8	Pass	Pass	60.0s	0.65KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 04/15/2005

Test Time: 03:15:29 AM

User Name: Glen Kraly

Device Tested

Model Number: box F

Serial Number: 120 amp 9thru 10 lds in HE.

Setup Filename:

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	25	1	Pass	Pass	60.0s	0.65KV	0.0microamps
2	DC Withstand	25	2	Pass	Pass	60.0s	0.65KV	0.0microamps