Thermometer Hipot 32 pin Connector

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 07:02:12 PM

User Name:

Device Tested

Model Number: box h

Serial Number: CY1 TEMP. SENSOR LDS

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 07:17:45 PM

User Name:

Device Tested

Model Number: box h

Serial Number: SPARE 1TEmp.SENSOR wire

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 07:20:50 PM

User Name:

Device Tested

Model Number: box h

Serial Number: SPARE2 TEMP. WIRE

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 06:32:48 PM

User Name:

Device Tested

Model Number: box h

Serial Number: LHE TEMP. SENSOR

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 06:57:21 PM

User Name:

Device Tested

Model Number: box h

Serial Number: DH LINE TEMP.SENSOR LDS

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps

Test Instruments Used

Test Model #	Test Serial #	Calibration Due Date
7550DT	9111100	02/01/2004

Test Date: 10/04/2005

Test Time: 06:48:06 PM

User Name:

Device Tested

Model Number: box h

Serial Number: CY2 TEMP. SENSOR LDS.

Setup Filename: Leads In Air & He.

Results

	Test Type	Memory	Step	Pass/Fail	Test Result	Timer	Parameter 1	Parameter 2
1	DC Withstand	29	1	Pass	Pass	60.0s	0.20KV	0.0microamps