

# Top Plate Distortion

*Meyer Tool & Mfg., Inc.*

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

(708) 425-9080

FAX (708) 425-2612

**CERTIFICATE OF CONFORMANCE**

**CUSTOMER:** LBNL

**P.O. #:** 6704950

**DESCRIPTION:** DFBX-H Feed Box 24C362

**QTY.:** 1

**MTM PROJECT #:** 00918

Movement of Top Plate during Vacuum Vessel Weldment-Negligible.

Certified by:  \_\_\_\_\_

Date: 10/18/05