

Lead Chimney Straightness and Bellows Offset Report



Meyer Tool & Mfg., Inc.

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

INSPECTION REPORT

708/425-9080

FAX: 708/425-2612

Job No.: 918
 Customer: LBNL
 Description: FEED BOX A
 MTM Dwg/Item No.: _____
 Qty Total: 1
 Qty Inspected: 1

Inspected By: EK/TKK
 Date: 2/22/2005
 MTE and Set-up: _____
 (Tag or Description) _____

Dimension/Tolerance or Characteristic/ Specification	Results ^{(1), (2)}	(3)
LEAD CHIMNEY	Subjct - 0035 OP40	
STRAIGHTNESS	< 1mm OK	
LEAD CHIMNEY	Subjct 0035 OP40	
BELLWS OFFSET	< .5mm OK	

Nonconformance Disposition: _____

Disposition By: _____ Date: _____

NOTES: 1. Record value of all out of tolerance/specification dimension/characteristics. Unless required to record actual values, it is sufficient to report dimensions or characteristics within tolerance or specification as "OK".
 2. Asterick (*) all nonconformances.
 3. Consecutively number all nonconformances.