

Pipe Clearance Inspection

Meyer Tool & Mfg., Inc.

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

(708) 425-9080

FAX (708) 425-2612

CERTIFICATE OF CONFORMANCE

CUSTOMER: LBNL

P.O. #: 6704950

DESCRIPTION: DFBX-D Feed Box 24C362

QTY.: 1

MTM PROJECT #: 00918

Piping Spools Clearance-Pipings Spools were visually inspected. Meyer and Fermilab personnel reviewed all clearances less than 12 mm. These clearances were all corrected through repositioning or G10 stand offs.

Certified by: Edward C. Bruner

Date: 2/1/05