Lead Chimney Straightness and Bellows Offset Report

Meyer Tool & Mfg., Inc.

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

708/425-9080
FAX: 708/425-2612

INSPECTION REPORT

Job No.: 918
Customer: LBNL
Description: FEED BOX F
MTM Dwg/Item No.:
Qty Total:
Qty Inspected:

Inspected By: EKC/TKK
Date: 2/10/2005
MTE and Set-up:
(Tag or Description)

Dimension/Tolerance or Characteristic/ Specification	Results (1), (2)	(3)
LEAD CHIMNEY STRAIGHTNESS	SUBJOB- 0015 OP40 <1 mm OK	
LEAD CHIMNEY BELLOWS OFFSET	SUBJOB- 0015 OP40 < .5 mm OK	

Nonconformance Disposition:

Disposition By: Date:

NOTES:
1. Record value of all out of tolerance/specification dimension/characteristics. Unless required to record actual values, it is sufficient to report dimensions or characteristics within tolerance or specification as "OK".
2. Asterick (*) all nonconformances.
3. Consecutively number all nonconformances

Rev. 9/30/93
JGC