Pipe Clearance Inspection

Meyer Tool & Mfg., Inc.
4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453
(708) 425-9080
FAX (708) 425-2612

CERTIFICATE OF CONFORMANCE

CUSTOMER: **LBNL**

P.O. #: **6704950**

DESCRIPTION: **DFBX-F Feed Box 24C395**

QTY.: **1**

MTM PROJECT #: **00918**

☑ Piping Spools Clearance-Pipings Spools were visually inspected. Meyer and Fermilab personnel reviewed all clearances less than 12 mm. These clearances were all corrected through repositioning or G10 stand offs.

Certified by: _____

Date: 6/30/05