

Pipe Clearance Inspection

Meyer Tool & Mfg., Inc.

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

(708) 425-9080

FAX (708) 425-2612

CERTIFICATE OF CONFORMANCE

CUSTOMER: LBNL

P.O. #: 6704950

DESCRIPTION: DFBX-G Feed Box 24C352

QTY.: 1

MTM PROJECT #: 00918

Piping Spools Clearance-Pipings Spools were visually inspected. Meyer and Fermilab personnel reviewed all clearances less than 12 mm. These clearances were all corrected through repositioning or G10 stand offs.

Certified by:



Date:

1/10/05