Lead Chimney Straightness and Bellows Offset Report

Meyer Tool & Mfg., Inc.

4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453

708/425-9080
FAX: 708/425-2612

INSPECTION REPORT

Job No.:	918	Inspected By:	ECK/TKK
Customer:	LBNL	Date:	7/29/05
Description:	FEED BOX H	MTE and Set-up:	
MTM Dwg/Item No.:		(Tag or Description)	
Qty Total:	1		
Qty Inspected:	1		

Dimension/Tolerance or Characteristic/ Specification	Results (1), (2)	(3)
LEAD CHIMNEY	Subjob - 0030 OP40	
STRAIGHTNESS	< 1 MM OK	
LEAD CHIMNEY	Subjob - 0030 OP40	
BELLOWS OFFSET	< .5 MM OK	

Nonconformance Disposition: _____

Disposition By: _____ Date: _____

NOTES:
1. Record value of all out of tolerance/specification dimension/characteristics. Unless required to record actual values, it is sufficient to report dimensions or characteristics within tolerance or specification as "OK".
2. Asterick (*) all nonconformances.
3. Consecutively number all nonconformances.

Rev. 9/30/93
JGC