

# Pipe Clearance Inspection

*Meyer Tool & Mfg., Inc.*  
4601 SOUTHWEST HWY., OAK LAWN, ILLINOIS 60453  
(708) 425-9080  
FAX (708) 425-2612

**CERTIFICATE OF CONFORMANCE**

**CUSTOMER:** LBNL  
**P.O. #:** 6704950  
**DESCRIPTION:** DFBX-H Feed Box 24C362  
**QTY.:** 1  
**MTM PROJECT #:** 00918

Piping Spools Clearance-Pipings Spools were visually inspected. Meyer and Fermilab personnel reviewed all clearances less than 12 mm. These clearances were all corrected through repositioning or G10 stand offs.

Certified by:



Date:

10/18/05